

NO. OF COPIES RECEIVED	2
DISTRIBUTION	
SAT. TAFE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

RECEIVED

JAN 16 1976

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

O.C.C.  
ARTESIA, OFFICE

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- 2. Name of Operator Texas International Petroleum Corporation (TIPCO) ✓ 3. Address of Operator P. O. Box 4520, Centenary Station, Shreveport, La. 71104 4. Location of Well UNIT LETTER <u>I</u> 1980 FEET FROM THE <u>South</u> LINE AND 990 FEET FROM THE <u>East</u> LINE, SECTION <u>10</u> TOWNSHIP <u>23S</u> RANGE <u>26E</u> NMPM. 15. Elevation (Show whether DF, RT, GR, etc.) 3300'GL, 3315'KB 12. County Eddy	5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/> 5. State Oil & Gas Lease No. 7. Unit Agreement Name 8. Farm or Lease Name Allied State 9. Well No. No. 1 10. Field and Pool, or Wildcat Canyon to Mid-Morrow
---	---

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	
P & A Canyon and commence production Middle Morrow			

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- The subject well (presently completed in Canyon - perf. 10,247-10,277') will be squeezed off w/200 sacks Class "H" cement.
- Drill cement and clean out to top of on/off tool @ 11,620'.
- Go in hole and latch on to on/off tool.
- Swab fluid level to 2500'.
- Run wireline tool and pull 1.875" blanking tool.
- If well does not flow, then swab.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jack M. Miles TITLE Manager of Drilling DATE Jan. 12, 1976

APPROVED BY W. A. Gressett TITLE SUPERVISOR, DISTRICT II DATE JAN 19 1976

CONDITIONS OF APPROVAL, IF ANY: