

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANITARY	1
FILE	1 ✓
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION

**RECEIVED**

FEB 5 1976

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. K-4538
7. Unit Agreement Name
8. Farm or Lease Name Allied State
9. Well No. 1
10. Field and Pool, or Wildcat <i>Carlsted</i> Undesignated (Canyon)
12. County Eddy

SUNDRY NOTICES AND REPORTS ON WELLS

O. C. C.

OFFICE

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT DEPTH. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator Texas International Petroleum Corp. ✓
3. Address of Operator P. O. Box 4520, Centenary Station, Shreveport, La. 71104
4. Location of Well UNIT LETTER <u>I</u> <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>990</u> FEET FROM THE <u>East</u> LINE, SECTION <u>10</u> TOWNSHIP <u>23S</u> RANGE <u>26E</u> NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 3300 GL

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/> Temp. abandon Canyon and recompleete in Middle Morrow.

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Pulled packer out of hole.
2. Picked up on/off tool. Went in hole, washed sand out to top of packer@ 11,620' & latched on to on/off tool. Blanking off Canyon.
3. Swab fluid level to 2500'.
4. Ran wireline and pulled 1.875" blanking tool.
5. Well started flowing on its own.
6. Cleaned well up and put in to sales line.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Manager of Drilling DATE January 30, 1976

APPROVED BY [Signature] TITLE SUPERVISOR, DISTRICT II DATE FEB 5 1976

CONDITIONS OF APPROVAL, IF ANY: