

ALLIED STATE #1
Workover Prognosis
Page 2

- K. If additional stimulation is necessary, acidize well with 3000 gal MOD 202 acid. Displace with 2% KCL w/Clay-Sta additives.
- L. Swab/flow back load and test.
- M. Put well on production.