

NO. OF COPIES RECEIVED	2
DISTRIBUTION	
SANTA FE	1
FILE	1 ✓
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION

RECEIVED

JUL 10 1974

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-68

O. C. C.

ARTESIAN OFFICE

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
2. Name of Operator Morris R. Antweil ✓	5. State Oil & Gas Lease No. -----
3. Address of Operator Box 2010, Hobbs, New Mexico 88240	7. Unit Agreement Name -----
4. Location of Well UNIT LETTER B, 990 FEET FROM THE North LINE AND 1980 FEET FROM THE East LINE, SECTION 17 TOWNSHIP 22-S RANGE 27-E N.M.P.M.	8. Farm or Lease Name Saik
	9. Well No. 1
	10. Field and Pool, or Wildcat Und. S. Carlsbad
15. Elevation (Show whether DF, RT, GR, etc.) 3122' GR	12. County Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	Completion <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD 11,690' PBTD 10,350' w/bridge plug. Tested well head w/4500 psi gas (N₂) pressure. OK. Perforated Strawn interval with 2 jet shots at each of the following depths: 10,308', 10,310', 10,316', 10,318', 10,320', and 10,326' (12 holes). Ran 2-3/8" tbg. and set packer @ 10,250'. Swabbed down. Good show of gas. Treated perfs w/250 gals mud acid. Treated @ 2 b/m w/5000 psi. ISIP 3300 psi. Swabbed well off. Flowed @ 500 to 800 MCFGPD rate. SITP 4000 psi. Prep to re-treat.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED R. M. Williams TITLE Agent DATE 3 July, 1974

APPROVED BY W. A. Gessett TITLE OIL AND GAS INSPECTOR DATE JUL 10 1974

CONDITIONS OF APPROVAL, IF ANY: