

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

MAR 11 1992

O. C. D.

WELL API NO.

30-015-21007

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.

NM 0515150

7. Lease Name or Unit Agreement Name

WESTFALL A COM

8. Well No.

1

9. Pool name or Wildcat

CARLSBAD, SOUTH (MORROW)

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☐

GAS
WELL ☒

OTHER

2. Name of Operator

SOUTHWEST ROYALTIES, INC. ✓

3. Address of Operator

P.O. BOX 953, MIDLAND, TEXAS 79702

4. Well Location

Unit Letter N : 660 Feet From The SOUTH Line and 1980 Feet From The WEST Line

Section 5 Township 23-S Range 27-E NMPM LEA Eddy County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3170.07' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. 2-6-92 SET 30 SX PLUG 11,511-11,400-TAG 11,300 DISPLACE WITH SALT GEL MUD
2. 2-7-92 SET 30 SX PLUG 10,978-10,878- CIRCULATE & DISPLACE WITH SALT GEL MUD
3. 2-7-92 SET 30 SX PLUG 9,840-8,740 CIRCULATE & DISPLACE WITH SALT GEL MUD
4. 2-10-92 CUT 5 1/2" CASING 7670' & LAY DOWN CSS
5. 2-11-92 SET 70 SX PLUG 7720'-7620' TAG 7580' CIRCULATE & DISPLACE WITH SALT GEL MUD
6. 2-11-92 SET 70 SX PLUG 5585'-5300' TAG 5280' CIRCULATE & DISPLACE WITH SALT GEL MUD
7. 2-12-92 SET 30 SX PLUG 3000'-2900' CIRCULATE & DISPLACE WITH SALT GEL MUD
8. 2-12-92 SET 30 SX PLUG 1845'-1745' CIRCULATE & DISPLACE WITH SALT GEL MUD
9. 2-13-92 CUT 8 5/8" 1490' & LAY DOWN CSS
10. 2-14-92 SET 70 SX PLUG 1540'-1440' TAG 1420' CIRCULATE & DISPLACE WITH SALT GEL MUD
11. 2-14-92 SET 70 SX PLUG 425'-325' TAG 350' CIRCULATE & DISPLACE WITH SALT GEL MUD
12. 2-14-92 SET 20 SX PLUG 350'-325' CIRCULATE & DISPLACE WITH SALT GEL MUD
13. 2-14-92 SET 10 SX PLUG AT SURFACE CIRCULATE & DISPLACE WITH SALT GEL MUD
14. 2-14-92 INSTALL DRY HOLE MARKER

Post ID-2
3-20-92
PFA

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Larry Murray

TITLE

Supervisor - American Oil

DATE

2-25-92

TYPE OR PRINT NAME LARRY MURRAY

TELEPHONE NO.

915-684-0074

(This space for State Use)

APPROVED BY

[Signature]

TITLE

Field Rep

DATE

8/3/93

CONDITIONS OF APPROVAL, IF ANY: