

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION  
P. O. BOX 7  
SANTA FE, NEW MEXICO 87501



Form C-103  
Revised 10-1-73

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.G.S.	
LAND OFFICE	
OPERATOR	<input checked="" type="checkbox"/>

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
K-4401	
7. Unit Agreement Name	
8. Farm or Lease Name	
State K-4401 <i>AM</i>	
9. Well No.	
1	
10. Field and Pool, or Wildcat	
South Carlsbad Morrow	
12. County	
Eddy	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT..." (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator
Hamon Oil Company <input checked="" type="checkbox"/>
3. Address of Operator
611 Petroleum Building, Midland, Texas 79701
4. Location of Well
UNIT LETTER C 1980 FEET FROM THE West LINE AND 660 FEET FROM
THE North LINE, SECTION 2 TOWNSHIP 24S RANGE 26E NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)
3269.5' Gr

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Set CIBP at 11,490' and dump 35' of cement on plug to plug off present Morrow perforations from 11,518' to 11,528' and 11,537' to 11,540'.
- Perforate Morrow zones from 11,262' to 11,268'; 11,322' to 11,328'; 11,336' to 11,342'; and 11,383' to 11,390'.
- Swab test and acidize.
- Swab test and sand frac if necessary.
- Work to begin approximately May 14, 1984.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Cecil H. Barton TITLE Production Engineer DATE April 25, 1984

APPROVED BY Leslie A. Clements TITLE Supervisor District II DATE APR 27 1984

CONDITIONS OF APPROVAL, IF ANY: