Original Signed By Mike Williams	JUL 23 1985
rive Production Supervisor	7-19-85
B. I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
Set 35 sx cement plug at 2676-2576', tag plug.	
Set 35 sx cement plug at 4820-4720'.	
Set plug 50' in and 50' out 5-1/2" stub, tag plug.	
to plugback well as follows:	os by badic nameoda
Verbal permission obtained from Mike Williams, NMOCD, Artesia, 7-18-	85 by Eddie Mahfood
7-18-85. Ran bottom hole pressure bomb.	
7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including a work) SEE RULE 1103.	estimated date of starting any proposed
Plugback X	
PULL OR ALTER CASING CHANGE PLANS CASING TEST AND CEMENT JOB COTHER	
TEMPORAPILY ABANDON COMMENCE DRILLING OPHS.	PLUG AND ABANDONMENT
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
Check Appropriate Box To Indicate Nature of Notice, Report or Othe NOTICE OF INTENTION TO: SUBSEQUENT	
4390' GR	Eddy ()
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
West LINE, SECTION 11 24S 23E NMPM.	
UNIT LETTER PEET FROM THE FEET FROM THE FEET FROM	Wildcat - Property
, Location of west	10. Field and Pool, or widcat
. Address of Operator	9. Well No.
Yates Petroleum Corporation	8. Form or Lease Name Trail "ACO" State
OIL X GAS OTHER. Plugback	A 5
SUNDRY NOTICES AND REPORTS ON WELLS IDO NOT USE THIS FORM FOR PROPOSALS TO CHILL OR TO DELPEN OR PLUG DACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	7, Unit Agreement Name
SUNDRY NOTICES AND REPORTS ON WELLS	
OPERATOR I/	5, State Oil 6 Gas Lease No. LG 2882
U.S.G.S.	Sa. Indicate Type of Lase State X Fee
SANTA FE, NEW MEXICO 87501	
DISTRIBUTION RECEIVED BY BOX 2088	Form C-103 Revised 10-1-78
STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT	
CTATE OF ASSIV MEXICI	