

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO. 30-015-21152
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No. 70440
7. Lease Name or Unit Agreement Name BEAR
8. Well No. 1
9. Pool name or Wildcat SOUTH CARLSBAD

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	
2. Name of Operator APACHE CORPORATION	
3. Address of Operator 2000 POST OAK BLVD., STE. 100, HOUSTON, TX 77056-4000	
4. Well Location Unit Letter <u>J</u> : <u>1650'</u> Feet From The <u>SOUTH</u> Line and <u>1980'</u> Feet From The <u>EAST</u> Line Section <u>17</u> Township <u>22S</u> Range <u>27E</u> NMPM <u>EDDY</u> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: RECOMPLETE TO THE ATOKA <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

12/4/95	RU service unit. Pull tbg
12/6/95	Set CIBP at 11,110'. Dump bail 8 sxs class "C" cmt & calc TOC @ 11,076'
12/7/95	RIH w/ tbg to 10,690'. Pmp 500 bbls 2% KCL to circ hole clean
12/12/95	Fire guns 5 SPF f/ 10,675' - 10,685', total 50 shots
12/13/95	Set up acid job w/ 1500 gals 15% NEFE acid w/ additives. Flush w/ 2% KCL
12/14/95	Flowed gas & wtr to tank, well died. RU swab good gas blow after each run
12/15/95	Swab about 200' fluid each run, gets gas blow, then well dies
12/18/95	SITP-1250#. RU swab. Swab 6BW w/light blow after each run
12/19/95	SITP-500#. IFL @ 10,200'. FFL @ SN. Rec 2 BW. SWI

RECEIVED
JAN 19 1996
OIL CON. DIV.
DIST. 2

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Carolyn Huntoon TITLE ENG. TECH DATE 1/12/95

TYPE OR PRINT NAME CAROLYN HUNTOON TELEPHONE NO. (713) 296-6240

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

*Received on 1/12/95
not cement
operator*