

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
WELL	
W.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2038
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease
State ☒ For ☐
5. State Oil & Gas Lease No.
L-4325

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE APPLICATION FOR PERMIT - 17 (FORM C-101) FOR SUCH PROPOSALS.)

RECEIVED

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐	2. Name of Operator Jake L. Hamon	3. Address of Operator 611 Petroleum Building, Midland, Texas 79701	4. Location of Well UNIT LETTER K, 1980 FEET FROM THE South LINE AND 1980 FEET FROM THE West LINE, SECTION 2 TOWNSHIP 24S RANGE 26E N.M.P.M.	5. Elevation (Show whether DF, RT, GR, etc.) 3284.8' Gr	6. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERSONAL REMEDIAL WORK ☒ TEMPORARILY ABANDON ☐ PULL OR ALTER CASING ☐ OTHER ☐ SUBSEQUENT REPORT OF: REMEDIAL WORK ☐ COMMENCE DRILLING OPERATIONS ☐ CASING TEST AND CEMENT JOBS ☐ OTHER ☐ ALTERING CASING ☐ PLUG AND ABANDONMENT ☐
7. Unit Agreement Name				8. Farm or Lease Name State L-4325	
9. Well No. 1				10. Field and Pool, or Whident Carlsbad Morrow, South	
11. County Eddy				12. County Eddy	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Set cement plug in 5-1/2" casing from 11,885' back to 11,860' to plug off present Morrow perforations from 11,875' to 11,885'.
(Note: This is the maximum amount of cement which can be set to leave room to perforate next zone.)
- Perforate Morrow Sand from 11,850' to 11,854'.
- Acidize perforations with 1,500 gals of 7-1/2% Morrow Acid.
- Test zone, if productive, no other work will be done. If non-productive, then:
- Set bridge plug at approximately 11,800' and dump 35' of cement on plug. Test plug to 5000#.
- Perforate Morrow zone from 11,486' to 11,496'.
- Acidize with 2000 gals of 7-1/2% Morrow acid.
- Work to begin immediately.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Cecil H. Barton TITLE Production Engineer DATE September 13, 1982
APPROVED BY Mike Walker TITLE SUPERVISOR, DISTRICT II DATE SEP 15 1982
CONDITIONS OF APPROVAL, IF ANY: