

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPI
(Other instructions
reverse side)TE*
re-Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-077534

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

Wood Canyon Unit

8. FARM OR LEASE NAME

Wood Canyon Unit

9. WELL NO.

1 Y

10. FIELD AND POOL, OR WILDCAT

Wildcat

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 24-T24S-R25E.

12. COUNTY OR PARISH

Eddy

New Mexico

1. OIL WELL ☐ GAS WELL ☒ OTHER

JUL 3 1975

2. NAME OF OPERATOR

Chaparral Production, Inc.

3. ADDRESS OF OPERATOR

4815 S. Harvard, Suite 305, Tulsa, OK 74135 O.C.C. OFFICE

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

1980' FNL and 1656' FEL NE/4

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3856 GR

3878 KB

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other)

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

16' conductor @ 30' cemented to surface

10 3/4" 40.5# casing @ 2867 KB w/2475 sacks

7" 26# and 23# @ 8496 KB w/300 sacks

4 1/2" 13.5# and 11.6# Liner 7966-12038' w/250 sacks.

Morrow perfs @ 11,941-47 (26 holes)

CIBP set @ 11,830' w/50' cement cap.

Wolfcamp perf 9828-9931 w/63 holes.

1. MIDD unit. Install BOP, Pull 4 1/2" packer and 2 3/8" tubing.
2. Set bridge plug @ 9250' w/50' cement plug on top.
3. Run 2 3/8" tubing and 7" packer and set @ 7875. Swab test top of 4 1/2" liner. If test in non productive pull 2 3/8" tubing and 7" packer.
4. Set 7" bridge plug @ 7600' w/50' cement on top.
5. Move out DD unit and move in casing pulling unit.
6. Cut off 7" casing @ 7375 and pull 7" casing.
7. Spot 100' cement plugs @ 5800, 4300, 2700, 1300 and 100'

RECEIVED
JUN 16 1975
U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

Frank J. Sanchez

TITLE

ENGINEER

DATE

June 11, 1975

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

APPROVED

JUL 2 1975

R. L. BEEKMAN

ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

U.S. GOVERNMENT PRINTING OFFICE: 1963-O-685229

847 - 485