

RECEIVED

FEB 28 1975

WELL WORK REPORT **O. C. C.** **ARTESIA, DEFE1** of _____Lease Name WOOD CANYON UNITWell Number #1Location NE/4 Sec. 24-T24S-R25E

Elevation _____ Perm. Datum _____

Eddy County, New Mexico.Down Hole
Condition
(after work)

Reason for Work _____

RECEIVED

FEB 26 1975

U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

Date	Operation
3-25-74	1980' FNL and 1650' FFL. Loc. will be ready Noon 3-26-74.
3-26-74	Loc. Will install 18" conductor pipe today.
3-27-74	Location
3-28-74	MIRUCT.
3-29-74	Will Spud today. Parrish Drlg Co., contractor.
3-30-74	Drlg @ 35', Spud 2:30 p.m. 3-29-74.
3-31-74	Drlg @ 45'.
4-1-74	Drlg @ 60'.
4-2-74 & 4-3-74	Drilling. No Report.
4-4-74	Drlg @ 75'.
4-5-74	Lost Tools in hole @ 112'. Now fishing for Tools. Drilling 15½" hole. Making 10-15' per 10 hr. day.
4-6-74 & 4-7-74	TD 112. Fishing for tools.
4-8-74	Jarring on tools.
4-9-74	No Report.
4-10-74	Spotted 1 bbl Acid around stuck tools still could not jar loose. Prepare to fish with Hydraulic Jars and Drill Collars.
4-11-74	Spotted 2 bbl Acid around fish. Let soak over night. Rigging up hydraulic jars and drill collars.
4-12-74	Run side door over shot with hydraulic jars and two drill collars, caught fish. Side door on over shot broke when started jarring. Pulled out of hole. Run 5½" over shot would not hold fish. Shut down for night. Will run 5" over shot.
4-13-74	Run 5" over shot w/hydraulic jars and two drill collars, caught fish. Jarred original fishing tools out of hole. Shut down over Easter week-end. Will repair rig and start up after Easter.
4-14-74	Shut down.
4-15-74	No Report.
4-16-74	Moving in larger Cable Tool Rig.

Signed _____