

RECEIVED

FEB 28 1975

WELL WORK REPORT

O. C. C.
ARTESIA, OFFICE
Page 2 of

Lease Name WOOD CANYON UNIT

Well Number #1

Location _____

Elevation _____ Perm. Datum _____

Down Hole
Condition
(after work)

Reason for Work _____

Date	Operation
4-17-74 & 4-18-74	Changing out Cable Tool Rigs.
4-19-74	Cable Tool Rig changed out will start to fish drilling tools today.
4-20-74	Rigged up fishing Tools and started jarring on fish.
4-21-74	Jarred on fish 8 hrs. Fish would not move-- spotted 3 bbls acid through 1" tbq left strain on fish over night. Tbg went to bottom of Fish.
4-22-74	Fish still would not move. Run string shot opposite bit. Recovered everything in hole except Drilling bit (Approx. 6' long) will try to fish bit.
4-23-74	Unable to recover bit. Prepare to start new hole.
4-24-74	New cellar dug. Now drilling hole to set Conductor Pipe.
4-25-74	Drill 24" hole to set conductor pipe.
4-26-74	30' of 16" conductor pipe set and cemented. Will start drilling today.
4-27-74	Start drilling out from under 16" Conductor pipe set @ 30'.
4-28-74 & 4-29-74	Drilling. No Report.
4-30-74	Drilling @ 80'.
5-1-74 & 5-2-74	Drilling. No Report.
5-3-74	Drilling @ 100'.
5-4-74	Last Bit and Stem in hole. Fished Stem and Bit.
5-5-74	Shut down waiting on new Stem.
5-6-74	Drig @ 115'.
5-7-74 to	Drilling. No Report.
5-10-74	Drilling @ 160'.
5-11-74 & 5-12-74	Drilling. No Report.
5-13-74	Drilling @ 170'.
5-14-74 to 5-16-74	Drilling. No Report.
5-17-74	Drig. @ 180'. Shut down two days for machine

Signed _____