

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

RECEIVED

JAN 20 '88

Form C-103  
Revised 10-1-73

|                        |   |
|------------------------|---|
| NO. OF COPIES RECEIVED |   |
| DISTRIBUTION           |   |
| SANTA FE               | 1 |
| FILE                   | 1 |
| U.S.G.S.               |   |
| LAND OFFICE            |   |
| OPERATOR               | 1 |

5a. Indicate Type of Lease  
State ☒ Fee ☐  
O. C. D. ARTESIA, OFFICE

5. State Oil & Gas Lease No.

IG 1443

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO OPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT - 1" (FORM C-101) FOR SUCH PROPOSALS.)

|  |  |
|--|--|
| 1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER-<br>2. Name of Operator<br>Coquina Oil Corporation<br>3. Address of Operator<br>P.O. Drawer 2960 Midland, TX 79702<br>4. Location of Well<br>UNIT LETTER 0, 660 FEET FROM THE South LINE AND 1980 FEET FROM THE East LINE, SECTION 16 TOWNSHIP 23S RANGE 26E NMPM.<br>15. Elevation (Show whether DF, RT, GR, etc.)<br>3352 GL | 7. Unit Agreement Name<br>8. Farm or Lease Name<br>State 16<br>9. Well No.<br>1<br>10. Field and Pool, or Wildcat<br>Carlsbad Morrow South<br>12. County<br>Eddy |
|--|--|

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

|  |  |  |   |
|--|--|--|---|
| PERFORM REMEDIAL WORK <input type="checkbox"/> | PLUG AND ABANDON <input checked="" type="checkbox"/> | REMEDIAL WORK <input type="checkbox"/>               | ALTERING CASING <input type="checkbox"/>      |
| TEMPORARILY ABANDON <input type="checkbox"/>   | CHANGE PLANS <input type="checkbox"/>                | COMMENCE DRILLING OPHS. <input type="checkbox"/>     | PLUG AND ABANDONMENT <input type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/>  | OTHER <input type="checkbox"/>                       | CASING TEST AND CEMENT JOBS <input type="checkbox"/> |   |

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plan to plug the well as follows:

1. Set retainer at 10,700' and pump 45 Sx cement below retainer.
2. Spot 35 Sx cement on top of retainer.
3. Load hole with mud.
4. Cut and pull 4 1/2" casing at + 8800'.
5. Spot 35 Sx cement 50' in and out of stub and tag.
6. Spot 35 Sx at 6854'.
7. Spot 35 Sx at 5350'.
8. Spot 45 Sx at 2800' and tag.
9. Spot 35 Sx at 650'.
10. Spot 10 Sx surface plug.

Plugging

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED \_\_\_\_\_ TITLE Field Forman DATE Jan. 20, 1988

APPROVED BY Mark Williams TITLE OIL AND GAS DIRECTOR DATE JAN 20 1988