

5-25 7:00 am - Flowing to pit, $\frac{1}{2}$ " choke,
TP 30 to 70 psig, gas with very heavy
water spray with intermittent slugs
of water

Cleaned up location. Released ~~the~~ rental equipment. Released crew
at 10:00 am. Too windy to rig up.
Flowed to pit throughout day.
At 5:30 pm, $\frac{1}{2}$ " choke, TP 40-80 psig
gas with heavy water spray with
occasional slugs.

Left flowing to pit overnight.

5-26 7:00 am - Flowing to pit, $\frac{1}{2}$ " choke,
TP - 70 to 80 psig, gas with very
heavy water mist

Met with Carter Hughes.

Carter to start checking well
Rigged down and moved out
Mack Chase unit