

Corinne B. Grace

Daily Report

Workover & Recomplete in Morrow Sands

Cueva Unit #1
Sec. 6-T23S-R26E
Sheep Draw Field
Eddy County, New Mexico

=====

4/16/96 7:00AM 90 PSI.

1 run 9600
2 run 10000 out w -0- change cups
3 run 10000
4 run F nipple 200' left
5 run 0 fluid 0 fluid Wait 1 hour.
6 run 0 fluid 0 fluid

12:34PM shut in with gauge in top.

4/17/96 7:00AM 350 PSI tubing shut in PSI

1 run fluid -0- F nipple, out with 200'
2 run -0- level -0- out

Shut in 9:05AM

4/18/96 6:45AM 420 PSI

1 run went to F nipple 0 fluid

8:30AM left on 10/64 choke, open to pit 10 psi.

4/19/96 6:45AM

1 run went to F nipple -0- fluid

Schlumberger perforated.

2:30PM making swab run -0- out

6:15PM

1 run fluid level 4200' out 1200'

2 run 4900'

3 run 5600'

4 run went to 6400' out with 8 to 10 bbls
changed cups.

5 run touched at 6900' went to 8400' 6 bbls

6 run went to PF nipple out with 8-10 bbls.

out with 3100' of fluid. 38 bbl out and
1 hour flowed heavy mist.

Midnight stopped swabbing. left on 10/64 choke to pit.

4/20/96 7:00AM

1 run fluid level 1200' went to 3500'

2 run 2400' out with 800'

3 run 2100' went to 3500'

4 run 3400' from surface out with -0- change cups

5 run 3400'

6 run 6900'

7 run 3500'

8 run 4900'

9 run went to PF nipple 200' fluid out

1:50PM shut in with gauge on top.