

SULPHATE AUNT #1
SECTION 3, T24S, R27E
EDDY COUNTY, NEW MEXICO

Oct. 30, 1975	Drilling out crevice.
Oct. 31, 1975	Drilling out crevice.
Nov. 1, 1975	Drilling out crevice.
Nov. 3, 1975	Drilling out crevice.
Nov. 4, 1975	Drilling out crevice.
Nov. 5, 1975	Drilling out crevice.
Nov. 6, 1975	Drilling out crevice.
Nov. 7, 1975	Drilling out crevice.
Nov. 8, 1975	Drilling out crevice.
Nov. 10, 1975	Drilling out crevice.
Nov. 11, 1975	Drilled 1293' to 1294' in anhy V.H.
Nov. 12, 1975	Drilled 1294' to 1295' in anhy V.H.
Nov. 13, 1975	Drilled 1295' to 1296' in anhy V.H.
Nov. 14, 1975	Drilled 1296' to 1297' in anhy V.H. Must work on crevice.
Nov. 15, 1975	Drilled on crevice.
Nov. 17, 1975	Drilled on crevice.
Nov. 18, 1975	Drilled on crevice.
Nov. 19, 1975	Drilled on crevice.
Nov. 20, 1975	Drilled on crevice.
Nov. 21, 1975	Drilled on crevice.
Nov. 22, 1975	Drilled on crevice.
Nov. 24, 1975	Drilled on crevice.
Nov. 25, 1975	Drilled on crevice.
Nov. 26, 1975	Drilled on crevice.
Nov. 28, 1975	Drilled on crevice.
Nov. 29, 1975	Drilled on crevice.
Dec. 1, 1975	Drilled 1297' to 1299' in anhy V.H., tools working well but formation very hard, line wearing badly.
Dec. 2, 1975	Drilled stranded line.