

SULPHATE AUNT #1  
SECTION 3, T24S, R27E  
EDDY COUNTY, NEW MEXICO

May 14, 1976 Drilling out crevices and reaming.  
May 17, 1976 Drilling out crevices and reaming.  
May 18, 1976 Drilling out crevices and reaming.  
May 19, 1976 Drilling out crevices and reaming.  
May 20, 1976 Drilling out crevices and reaming.  
May 21, 1976 Drilling out crevices and reaming.  
May 24, 1976 Drilling out crevices and reaming.  
May 25, 1976 Drilling out crevices and reaming.  
May 26, 1976 Drilling out crevices and reaming.  
May 27, 1976 Drilling out crevices and reaming.  
May 28, 1976 Drilling out crevices and reaming.  
May 31, 1976 Drilling out crevices and reaming.  
June 1-July 13, 1976 Drilled out crevices to 1200', bull belt stolen from rig.  
July 30, 1976 Put on old belt (used) and Reamed.  
July 31, 1976 Reamed.  
August 1, 1976 Reamed, Broke old belt.  
August 17, 1976 Spliced belt, Reamed.  
August 18, 1976 Reamed, Broke belt.  
September 5, 1976 Spliced belt, Reamed, Broke belt.  
September 24, 1976 Put on new belt, Cleaned out.  
September 25, 1976 Cleaned out.  
October 12, 1976 Cleaned out.  
October 24, 1976 Cleaned out.  
November 10, 1976 Cleaned out.  
November 21, 1976 Drilled. Cleaned out.  
December 4, 1976 Drilled. Cleaned out.  
December 13, 1976 Drilled. Cleaned out.  
December 19, 1976 Drilled. Cleaned out.

RECEIVED

JAN 28 1977

G. C. C.  
ARTESIA, OFFICE

RECEIVED

JAN 27 1977

U. S. GEOLOGICAL SURVEY  
ARTESIA, NEW MEXICO