

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	/
FILE	/
U.S.G.S.	
LAND OFFICE	
OPERATOR	/

RECEIVED

NEW MEXICO OIL CONSERVATION COMMISSION 1978

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

O. C. C.  
ALBUQUERQUE, OFFICE

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. K-4542
7. Unit Agreement Name
8. Farm or Lease Name Sulphate Uncle
9. Well No. 1
10. Field and Pool, or Wildcat Wildcat
12. County Eddy

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator Corinne Grace
3. Address of Operator P. O. Box 1418, Carlsbad, New Mexico 88220
4. Location of Well UNIT LETTER L 1980 FEET FROM THE South LINE AND 660 FEET FROM THE West LINE, SECTION 23 TOWNSHIP 24S RANGE 27E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 3204.6

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/> CHANGE PLANS <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Drilled to a TD of 2023'  
13 3/8" casing set to a depth of 638'  
Hole size out of casing 12 1/4"  
Run tubing to T.D. load with mud  
Spot a 100' plug from 1900' to 2000' with 100 sacks cement  
1400' to 1500' with 100 sacks cement (top of salt)  
590- to 690' with 100 sacks - calcium chloride 2% tag plug  
0' to 30' with 20 sacks  
Set marker

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Francis James Wildberger TITLE Agent DATE 10/16/78

APPROVED BY W. A. Gressett TITLE SUPERVISOR, DISTRICT II DATE OCT 18 1978

CONDITIONS OF APPROVAL, IF ANY:

Notify NMOCC in sufficient time to witness  
Plugging