

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

RECEIVED

OCT 17 1978

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

O. C. C.

ARTESIA, OFFICE

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER -	7. Unit Agreement Name
2. Name of Operator Corinne Grace	8. Farm or Lease Name Sulphate Uncle
3. Address of Operator P. O. Box 1418, Carlsbad, New Mexico 88220	9. Well No. 1
4. Location of Well UNIT LETTER <u>L</u> <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE, SECTION <u>23</u> TOWNSHIP <u>24S</u> RANGE <u>27E</u> NMPM.	10. Field and Pool, or Wildcat Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) 3204.6	12. County Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 110.

Drilled to a TD of 2023'
13 3/8" casing set to a depth of 638'
Hole size out of casing 12 1/4"
Run tubing to T.D. load with mud
Spot a 100' plug from 1900' to 2000' with 100 sacks cement
1400' to 1500' with 100 sacks cement (top of salt)
590- to 690' with 100 sacks - calcium chloride 2% tag plug
0' to 30' with 20 sacks
Set marker

11/2/78

Run tubing to 1930', Pumped 400 BBLs mud sealed hole.
Pumped 100 x 20 class H 1930'-1830' Pumped 100 x 20 class H 1805'-1705'.
Pumped 100 x 20 class H 270 gyp sand 640'-540'. Waited 1 1/2 hr.
Run wireline tagged plug to 605'. Ran 1 ft tubing and spotted
20 x 20 plug to surface. BT pumped job using Dave Robinson's job rig.
Mike Spitzfeld

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Granite Gas Wildberger TITLE Agent DATE 10/16/78

APPROVED BY W. A. Gussert TITLE _____ DATE 10-18-78

CONDITIONS OF APPROVAL, IF ANY:

Notify N.M.O.C.C. in sufficient time to witness

Plugging