CORINNE CRACE WHITE BABY # 1 SECTION 16, T2L3, R26 E EDDY COUNTY, NEW MEXICO

April 17, 1975	Broke down big bit had welder weld 3 hrs. didn't make any hole working on casing.
April 18, 1975	Rough rocks and stuff still falling in hole 4 hrs. need casining.
April 19, 1975	Sure need casing not doing any good though we would have casing today but didn't. 4 hrs.
April 20, 1975	Sunday didn't work on well today. Went to church.
April 21, 1975	Drilled most all day but didn't make any hole must have casing. Rock and stuff falling. 7 hrs.
April 22, 1975	Need casing bad stuff falling in lost about 2' of hole boday.
April 23, 1975	Went to Lubbock to find 16" casing found new also used pipe and a place that will deliver to Carlsbad
April 24, 1975	Stuff still caving in. Going to go back to 12" tools. Need casing bad.
April 25, 1975	Still having troble can't make any hole. Need some casing.
April 26, 1975	Made about 2' hole not doing any good. Need casing. Stuff still falling in.
April 27, 1975	Didn't work on well. Went to Church.
April 28, 1975	Charged out two hours. (Sure need casing)/
April 29, 1975	Still not making any hole. Drill hung up, got lose. Drill some more cave in. ect. need casing.
April 30, 1975	Have drilled hard all day made a little bit of hole still need casing to keep lock dirt and rocks.
May 1, 1975	Worked 5 hrs. Still the same drilling hole. Need casing
May 2, 1975	2 hrs. run out of gas.
May 3, 1975	Made some hole, things aren't going so good rock, sand, dir $\hat{\tau}_s$ trouble. 4 hrs.
May 4, 1975	Went to church
May 5, 1975	Broke cable on drill line must splice 2 hrs.
May 6, 1975	More trouble in hole.
May 7, 1975	Got loose got out of hole 4hrs.
May 8, 1975	Worked 7 hrs. Can't do any good hung up cave in caves in faster than you can drill it up. Need casing.

520)

33

. **`**•

215

ą