CORIDNE GRACE WHITE BABY #1 SECTION 16, T245, R26E EDBY COUNTY, MSW MEXICO

0 - 1 / 2 D Z I V 2 D

some more work on the reamer.

G. L. G. Anteria, office

- March 3, 1975 hun tools for a while then cleaned but had for a while. Had to weld on extra iron on bity to be sure it means the hole good and round.
 - March 4, 1975 Will be cleaning out and reaming hole to be able to set 16" pipe.
 - March 5, 1975 Have been runing and cleaning out hole worked 6 hrs..
 - March 6, 1975 Have been drilling on hole. Made a run up in pipe 18" and hung up tools in a flat place in casing tools hung up in big pipe new.
 - Marcn 7, 1975 Didn't work. Are drill today.
 - March 8, 1975 Have had tools hung up for a while today. But got loose and are reaming out hole now for the 16" pipe.
 - March 9, 1975 Worked 4 hrs. today, tools only hung up once. Reamed out a lot of hole.
 - March 10, 1975 June was sick, took her to Doctor did'nt work at all on well.
 - March 11, 1975 Made a lot of hole reaming. But tools hung up and broke cable fished for tools caught them three times, but did'nt get them out today.
 - March 12, 1975 Have been fishing for tools all morning, caught them and brought them out about 1:10 pim. today. Worked 5 hrs. mained out.
 - March 13, 1975 Back drilling again tools falling plotty good. Stuff still slipping off and rocks falling in an tools. Worked 9 hours today.
 - March 14, 1975 Did'nt measure but should be back close to 270' still rocks falling in
 - March 15, 1975 Worked 2 hours, broke the jarrs shut down the rest of the day.
 - March 16, 1975 Did'nt work today on well. Went after tools.
 - March 17, 1975 Worked 4 hours.

(

- March 18, 1975 Worked 8 hours welding on jarrs and tunning up motor trying to get out of hole.
- March 19, 1975 Worked on jarrs, motor, rig, ect. Worked 8 hours.
- March 20, 1975 Had Bryon Stork out on job. He worked on power plant. No charge today to M.P. Grace and CO.
- March 21, 1975 Worked all day. Cleaned out more hous didn't measure out.
- March 22, 1975 Didn't work today cracked the big bit must weld it up.
- March 23, 1975 Didn't work on well Sunday.
- March 24, 1975 More on tools set.