

**May 1996 Workover  
Morning Report**

**5/20 Mon. MIRU. Pride Petroleum Services. Long stroked the pump, no pump action. Unable to unseat pump. Backed off rods 174 down. Pulled rods. SIFN.**

**5/21 Tues. Bleed casing down. NU BOP. Released TAC, pulled 8 stands to fluids. Swabbed tbg to csg. Pulled out 71 stands back to rods. Pulled on rods and rods pulled free. POOH w/remaining rods (pull rod had pulled out of pump). Swabbed and pulled 81 stands. Swabbed tbg down to pump. POOH w/ tubing. Removed pump from SN. Closed BOP. SIFN.**

**5/22 Wed. Opened well, slight vacuum. RIH with the Bull Plug, 1 jt MA, 4' PS, S/N, 20 jts, TAC, and 308 jts. Set TAC w/14 pts. Removed BOP. Flanged up. RIH w/ rods and pump as follows:**

**(Marvin where do I get this information from?)**

**Checked every break going back in. Seat pump, hung well on, hooked up flow line. Load tubing, check pump action. RDMO.**