

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-015-21444
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	VA-1132
7. Lease Name or Unit Agreement Name	Big Freddy Unit
8. Well No.	3
9. Pool name or Wildcat	Sitting Bull Falls Morrow

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	
2. Name of Operator YATES PETROLEUM CORPORATION	
3. Address of Operator 105 South 4th St., Artesia, NM 88210	
4. Well Location Unit Letter <u>F</u> : <u>2310</u> Feet From The <u>North</u> Line and <u>2410</u> Feet From The <u>West</u> Line Section <u>36</u> Township <u>23S</u> Range <u>22E</u> NMPM <u>Eddy</u> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4410' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: Clean out to original TD <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

11-14-98 - Nipped down BOP. Cut casing off. Nipped up tubing head and 5K BOP. Shut down.

11-15-98 - TIH with 4-3/4" bit, drill collars and tubing. Tagged cement at 4436'. Rigged up swivel. Drilled out cement. Fell out of cement at 4623'. Pressure tested casing to 2000 psi, OK. TOOH with bit, drill collars and tubing. TIH with 4-3/4" mill shoe with wires and tagged up at 6641'. Made 6'. TOOH with tubing, drill collars and mill shoe. Had 1 joint of 2-3/8" tubing with flare collar on bottom. TIH with 4-3/4" string mill, drill collars and tubing. Worked string mill from 4590-4603'. TOOH with string mill, drill collars and tubing. TIH with 4-3/4" bit, drill collars and tubing. Tagged up at 5572'. Drilling at report time.

11-16-98 - Drilling. Made 12-1/2'. Started TOOH. Rig broke down. Shut down. Prep to change out pulling units.

11-17-98 - Changed out pulling units. TOOH with 4-3/4" bit. TIH with 4-3/4" mill shoe with wires, drill collars and tubing. Tagged up at 5583'. Made 6-1/2' to 5589.5'.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

CONTINUED ON NEXT PAGE:

SIGNATURE Rusty Klein TITLE Operations Technician DATE Nov. 24, 1998
TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505/748-147

(This space for State Use)

ORIGINAL SIGNED BY TIM W. GUM
DISTRICT II SUPERVISOR

APPROVED BY _____ TITLE _____ DATE 12-01-98

CONDITIONS OF APPROVAL, IF ANY: