-	~		-	
NU. OF COPIES RECEIVED				Form C-103
DISTRIBUTION				Supersedes Old
ANTAFE	NEW MEXICO OIL CON	SERVATION COMMISSION		C-102 and C-103 Effective 1-1-65
FILE		RECE	EIVE	D
U.S.G.3.				a. Indicate Type of Lease
LAND OFFICE			F 107	State X Fee
OPERATOR /		DEC	5 1975 ₃	. State Oil & Gas Lease No.
·				1-4595
SUNDAY	NOTICES AND DEDODTS ON		C. C.	
SUNUR (00 NOT USE THIS FORM FOR PROPE USE MAPPLICATION	NOTICES AND REPORTS ON BALS TO DRILL OF TO DEEPEN OF PLUG N FOR PERMIT -" (FORM C-101) FOR SUI		K	
	FIGH FEAMIN - (FORM CETOI) FOR SU	LA PROPOSALS.)		. Unit Agreement Name
G.L GAS WELL X	OTHER-			
Name of Operator				, Farm or Lease Name
Convine Oil Course				
<u>Coquina 011 Corpor</u>	ation			Jake State
P. 0. Drawer 2960, Midland, TX 79701				0. Field and Pool, or Wildcat
	0100			
UNIT LETTER C,	2180_ FEET FROM THE West	LINE AND660 1	FEET FROM	pdr. Crawford Penn
			Ň	
THE North LINE, SECTION	<u>36</u> TOWNSHIP <u>24S</u>	RANGE 26E	<u> </u>	
mmmmm		DE PT CP	P	innnittittitti
41111111111111111111111111111111111111	15. Elevation (Show whether		1	2. County
İmmunum minu		GL 3300'		Eddy
Check Ar	ppropriate Box To Indicate M	ature of Notice, Repor	t or Other	Data
NOTICE OF INT				EPORT OF:
PERFORM REMEDIAL WORK	PLUS AND ABANDON	REMEDIAL WORK	Π	ALTERING CASING
TEMPORARILY ABANDON		COMMENCE DRILLING OPNS.	Ē	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB	П	
		OTHER	Dril	ling to completion
OTHER				μ_
 Describe Proposed or Completed Oper wor!) SEE RULE 1103. 	ations (Clearly state all pertinent det	ails, and give pertinent dates,	including es	timated date of starting any proposed
Spudded a 17 1/2" hole	on 4-27-75. Drld to 6	05° and ran 20° its	13 3/8"	61# STC casing and cot
0 605'. Cemented w/550	sxs lite Wate, nlus 2	$n_{0} \propto n_{0} = 10$	$\begin{bmatrix} 10 & 0 \\ 0 & 1 \end{bmatrix} = \begin{bmatrix} 10 & 0 \\ 0 & 1 \end{bmatrix}$	1/1# Elocolo in all
cement. Circ approxima	telv 50 sxs to nit D	isplaced plug w/88		D @ 1:45 PM, 4-29-75. WOC
18 hrs. Drld 12 1/4" h	ole to 8295 and ran 2	11 i + c = 0.5/8" / 0.5	Л74 N	$D \in 1.45$ PM, $4-29-75$. WUU
and set @ 8295" and cem	ented w/1000 sys lite !	d_{ato} plus 200 sys (, 4/π N-	1/4 celoflake in all cmt.
Displaced plug w/513 BE		75 WOC 96 bbc	Tastad	csg to 2000 psi - held OK.
Drid 8 1/2" hold to 10	6/0! Pop 57 ito 7 5/	-75. WUU OU HITS.		csg to 2000 psi - neid UK.
Bottom of lines Q 10 52	$3^{+} \text{(all 57 Jls 7 5/6)}$	5 23.05# 5-95 HYO)		iner. Top of liner 8028',
Bottom of liner @ 10,63	J . Cemented W/385 SX	s uldss H W/5# Sall	L & 3/4%	U-31. Uisplaced plug
W/210 DATTELLS 12.07 MU	Jan Bumped plug W/1500	µsi @ /:45, 6-25-/	75, WUC	25 hrs. Tested liner to
production balan 7 5 (0)	10 b 1/2 note to $11,9$	DD JULY 25, DST	's & log	information indicate no
production below / 5/8"	iner. Possible comp	letion in Strawn.	TD @ 11	,955'. Plugging back to
TU, OUU . Kan DP in hold	e open ended to 11,700	Set 35 sxs plug	j@11,7	00', 35 sxs plug @ 11,300'
35 sxs @ 10,700'. All	cement Class H. PBTD	10,600'. July 26,	thru Au	gust 29, moving out
rotary tool & WO comple	tion. 9-18-75, moved	in, rigged up PU.	Ran 7 5	/8" csg scraper, PU 179
jts 2 5/8" 4.6# N-80 Bu	ttress tbg to 6889'. 🤉	9-19-75, RU reverse	e unit.	Drld 15' cement. Circ
clean. Ran tbg to 7350	'. 9-20-75, drld cemer	nt from 7350' to 73	380'. R	an the to 7949'. Hit
another plug. Drld 70'	cement. Ran tbg to 84	485'. Circ hole fo	or 2 hrs	w/10# brine. 9-22-75.
testing. 9-24-75, drld	7993'-8028', top of l	iner. Ran 6 1/2" b	oit and	scraper to 8030', hit
bridge. Drld to 8060'.	Pushing plug down ho	le. Gas pocket sur	faced.	Circ. hole 1 hr. (OVER)
8. I hereby certify that the information at	ove is true and complete to the best	of my knowledge and belief.		
1.06 . 0				
IGNED Man Dear	2. Alan Bump	Engineering Asst.		DATE 12-4-75
* (* - 1	Faire			
PPRCYED ay	Set SU	PERVISOR, DISTRICT I	Ц.	DATE DEC 101975
CONDITIONS OF APPROVAL, IF ANY:		. <u> </u>		
UNDELIONS OF AFEROTAL, IF ANTE				

(CON'T)

Prep to set CIBP @ 10,614'. 9-25, ran Gamma Ray, Correlation log from 10,614' to 10,000'. Ran Howco 7 5/8" CIBP. PBTD 10,600'. 9-27-75, swab prior to perf. Perf w/thru tbg gun, 2 JSPF from 10,507'-10,520'. 13' and 26 shots. Test 10,507'-10,520'. 10-4-75, squeeze perfs, tested squeeze to 2150 psi for 15" - held OK. Pulled tbg to 7900'. Ran tbg to 10,509.51', re-perf from 10,507'-10,515' w/2 JSPF - set pkr. 10-5-75, thru 10-10 test. Removed tbg, unseated pkr, cleared tbg & casing w/70 BW. Pulled out of hole w/tbg & pkr. Ran and set Howco retainer to 10,487'. Squeezed perfs to 5500 psi. PU retainer - reversed out approx 17 sxs cmt, Est 5 sxs below retainer & 78 sxs in formation. 10-11-75, POOH w/tbg. Ran cag scraper to 10,000'. 10-12-75, drld cement. 10-14-75, ran tbg (same design) to 10,600'. Tested squeeze to 1500 psi for 15" - held OK. 10-15-75, Pulled tbg, perf 10,509'-10,515', 2 JSPF. Re-ran tbg. 10-17-75, acidized w/500 gals 15% mud acid. 10-18-75, went in hole w/tbg. Punched to 10,427', shot hole 12' above pkr. Pressured up in csg, unable to circ. WIH w/2 jet shots to 5500' & gun stopped. POOH, checked sots, re-ran & shot 2 holes 16' above pkr. Unable to circ w/2000 psi on csg. 10-19-75, released pkr, circ 70 bbls to pit to clean tubing & csg. Pulled tbg. 10-22-75, ran 10,494.76' of 2 3/8" 8rd 4.7# EUE tbg. 10-20-23-75, tested. 10-24-75, acidized w/500 gal 15% mud acid - tested. 10-29-75, swabbed to 10,000' & acidized w/500 gal 15% acid - tested. 11-12-7 perf from 10,171'-180', 10,151'-159', 10,132'-140'. 11-14-75, attempted to unseat pkr, jumped up hole 10' & reset. Could not unseat. Pumped 60 bbls KCl @ 4560 psi. Pkr released. 11-16-75 set cast iron bridge plug @ 10,290'. Ran tbg to 10,139'. Tested. 11-17-75, perf 2 JSPF @ 10,132'-40', 10,151'-59', 10,171'-80'. 11-20-75, acidized w/3000 gal 15% mud acid - con't to test. 11-22-75, unseated pkr, pulled tbg. Ran Correlation GR collar log from 10,000' to 9,000' Set CL3P @ 10,000'. 11-25-75, ran 9412.25' of 2 3/8" 4.7# N-80 Buttress tbg. 11-26-75, perf 9786'-92', 9777'-81', 9692'-96' w/2 JSPF. 11-26-75 thru 12-1-75, testing. 12-2-75, unseated pkr, POOH w/pkr & tbg. Ran Correlation log from 7450'-7000'. Ran 2000' of tbg in hole open ended. 12-3-75, ran tbg to 6500', circ 500 bbls wtr. POOH. Set CIBP @ 7410', spotted 20' of cement on CIBP. Started in hole w/pkr & tbg.