

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-015-21526

5. Indicate Type of Lease
STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name
Wilson Gas Com.

8. Well No.
1

9. Pool name or Wildcat
Carlsbad, Wolfcamp, East

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☐ GAS WELL ☒ OTHER

2. Name of Operator
Whiting Petroleum Corporation

3. Address of Operator
1700 Broadway, Suite 2300 Denver, CO 80290

4. Well Location
Unit Letter G : 1980 Feet From The North Line and 1980 Feet From The East Line
Section 1 Township 22S Range 27E NMPM Eddy County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3138 KB, 3117 GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☒	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐		CASING TEST AND CEMENT JOB ☐	
OTHER: ☐		OTHER: ☐	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

w/35' of

- Set CIBP @9145' ~~and dump 2 sks~~ cmt on top of plug.
> SPOT 100' cmt plug @ 7100'
- Cut off and recover 5600' of 4-1/2" csg.
- Spot a 100' cmt plug (50 sks) across csg stub (50' in & out). Tag
> SPOT 100' cmt plug @ 3600'
- Spot a 100' cmt plug (50 sks) across 8-5/8" csg shoe (50' above & below). Tag
- Spot a 30 sk cmt plug across 13-3/8" csg shoe @ 479'. Tag
- Spot a 25 sk cmt plug @ surface.
- Cut off csg 4' below ground level & weld on plate.
- Install P&A marker 4' above ground, clean and restore location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Douglas Sprague TITLE Div. Oper. Engr. DATE 1/29/97

TYPE OR PRINT NAME Douglas Sprague TELEPHONE NO.

(This space for State Use)

APPROVED BY Jim W. Gurn TITLE BGA District Supervisor DATE 2-10-97

CONDITIONS OF APPROVAL, IF ANY: Notify N.M.O.C.C. in sufficient time to witness Tag.

Plugging mud:
10# Brine w/25# gel
per barrel.