. NM OIL CONS. COMMISSION Jrawer DD

Form 9-331	Artesia, NM 88210	
Dec. 1973		Form Approved.
	UNITED STATES	Budget Bureau No. 42-R1424 5. LEASE
	DEPARTMENT OF THE INTERIOR	<u>NM-0415688-A</u>
<del>-</del>	GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUND (Do not use t reservoir, Use	RY NOTICES AND REPORTS ON WELLS this form for proposals to drill or to deepen or plug back to a different e form 9-331-C for such proposals.)	7. UNIT AGREEMENT NAME
1. oil well	- gas -	8. FARM OR LEASE NAME 01d Indian Draw Unit
	OF OPERATOR	9. WELL NO.
_Amoco	Production Company 🗸	6 10. FIELD OR WILDCAT NAME
	SS OF OPERATOR	Indian_Draw_Delaware
4. LOCAT	Box 68, Hobbs, New Mexico 88240 ION OF WELL (REPORT LOCATION CLEARLY. See space 17	11 SEC T D M GE C
00104.)	RFACE: 2002' FSLX 1721' FWL	18-22-28
AT TO	P PROD. INTERVAL: (Unit K, NE/4,SW/4)	12. COUNTY OR PARISH 13. STATE Eddy NM
	APPROPRIATE BOX TO INDICATE NATURE OF NOTICE.	14. API NO.
REPOR	T, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
	FOR APPROVAL TO: SUBSEQUENT REPORT OF:	3088.3' GL
FRACTURE SHOOT OR REPAIR WE		VED BY ROUR 2
PULL OR A MULTIPLE	ALTER CASING APR 3	(NOTE: Report results demultiple mpletion or zone 0 1984 change on Forfi 9-330.)
CHANGE Z( ABANDON*		
(other)		C. D. GREAT CALL CALL CALL CALL CALL CALL CALL CA
17. DESCR	IBE PROPOSED OR COMPLETED OPERATIONS (Clearly stating estimated date of starting any proposed work. If well is d	
includir measur	ng estimated date of starting any proposed work. If well is d red and true vertical depths for all markers and zones pertiner	e all pertinent details, and gives pertinent dates, irrectionally drilled, give subsurface locations and nt to this work.)*
Proposi 32061	e to perforate and acidize additional Del	laware pay in the interval 3192'-
Move i	and convert to injection per the followir n service unit and pull rods, pump, and t	ubing RIH with 3-3/8" casing
gun and	d perforate the Delaware interval 3192'-3	$3206'$ with 4 DPJSPE at $90^{\circ}$ or
120° pi	nasing. RIH with RBP, retrieving head, p	packer with unloader and tubing
3237'-:	P at ±3300'. Raise up and set packer at 3256' with 1900 gals of 15% NE HCL acid w	3220 ACIDIZE the interval
bottom	perfs with 2% KCL fresh water. Release	nacker and latch onto PPD
кыр ат	==3230° and set packer at ±3100'. Aridiz	e the interval 31921_32061 with
1400 ga	al of 15% NE HUL acid with additives. Fi	ush acid to bottom porfs with
2% KUL	Tresh water. Release packer and latch o	into PRP Drop down and recet
KBP at	$\pm 3300$ W Kaise up and set packer at $\pm 310$	10'. Swah to recover load Re-
Subsurface	Safety Valve: Many and Tune	J.Nash, HOU Rm 4.206 1-CMH (OVE Set @Ft.
PPROVE	Dry y that the foregoing is true and correct	
APR 2SIGNAR	hard M. Herry TITLE Admin. Analys	t 12-8-83
B. The Har	(This space for Federal or State off	
JACOCTOR NG DIST <b>BIPPR</b> EMERIA		
TO DISTRUCT ENGLA	VEER TITLE	DATE
Vu	of Approval, IF ANY: bal Approval - Leter Ch	ester 12/11/83

\*See Instructions on Reverse Side

- 4×. \*\*\*

**ACTING D** 

c/-871

lease packer and latch onto RBP. POH. RIH with 2-3/8" tubing with seating nipple on bottom. Land at ±3285' and run rods and pump. Move out service unit. Pump test to evaluate production characteristics. Move in service unit and POH. RIH with injection packer and plastic coated tubing. Set packer at ±3100'. Displace casing with packer fluid. Move out service unit. Commence water injection at a maximum of 300 psi surface injection pressure. \* Approval was received to convert to injection by NMOCD Administrative Order No. WFX-520.