(June 1990) DEPARTMENT BURFAU OF La	ED STATES Dr r DI OF THE INTERIOR Artesia, AND MANAGEMENT	NE 8821(Ppires: March 31, 1993 5. Lease Designation and Serial No.
Do not the this form for proposals to drill Use "APPELICATION FOR	ND REPORTS ON WELLS or to deepen or reentry to a different reservoir PERMIT—' for such propagation	 b If Indian, Allottee or Tribe Name 7. 7. If Unit or CA, Agreement Designation
CARL SUBMIT	IN TRIPLICATE O. C. D. ARTESIA, OFFICE	
I. Type of Well ARTESIN		8. Well Name and No. LAGUNA GRANDE #1
2. Name of Operator Bettis, Boyle & Stovall		9. API Well No. 30-015-21636
3. Address and Telephone No. P.O. Box 1240, Graham, TX 764	50 817-549-0780	10. Field and Pool, or Exploratory Area Wildcat-Bone Springs
4 Location of Well (Footage, Sec., T., R., M., or Survey Der 1380' FSL & 990' FEL, Sec. 28		11. County or Parish, State Eddy Co., NM
) TO INDICATE NATURE OF NOTICE, REP	PORT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION	N
Notice of Intent	Abandonment Recompletion	Change of Plans
Subsequent Report	Plugging Back	Water Shut-Off
Final Abandonment Notice	Altering Casing Other	Conversion to Injection Dispose Water Note Report results of multiple completion on Weil Completion or Recompletion Report and Log form 1
 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled. give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* 9/1/94 - Miru Cobra Well Ser., ND wellhead, NU BOP, TOOH w/ tbg., SIFN. 9/2/94 - RU Halliburton Logging Ser., TIH w/ 7-5/8" CIBP, set @ 6691' dump 6 sx cement on 9/2/94 - RU Halliburton Logging Ser., TIH w/ 7-5/8" CIBP, set @ 6691' dump 6 sx cement on CIBP. Run GR/CBL/CCL from 6691-4000'. Log show good cement bond, POOH w/ logging CIBP. Run GR/CBL/CCL from 6691-4000'. Log show good cement bond, 6598-6600, 6602- 		
tool. PU & TIH W/ 4 CSg gun, peri branches, begin running tbg in hole. 04, 1 SPF total 18 holes. POOH, RD loggers, begin running tbg in hole. 0/3/94 - Finish TIH to 6608' W/ 2-7/8" tbg. Acidize perfs W/ 1250 gals 7-1/2% NEFE acid.		
9/3/94 - Finits Finite RU to swabbing on well. RU to swab, swabbing on well. 9/4/94 - 13 hrs. SITP = 100 PSI. RU to swab, IFL = 4400' from surface. Swab dry in 6 hrs. 9/5 thru 9/6 SI for holiday. 9/7/94 - 44 hrs. SITP = 475 PSI. Bled well down in 15 min., dry formation gas. RU to swab.		
SIFN. 9/8/94 - 13 hrs. SITP = 50 PSI. Continued to swab well, prepared to frac. 9/8/94 - 13 hrs. SITP = 70 PSI. RU Western Co. to frac perfs w/ 29,000 gals. gel. ISIP		
= 900 PSI. 9/10/94- 14 hrs. SITP = 50 PSI, opened well up, flowback 2 BLW & died, RU to swab, swabbed well.		
9/11 thru 9/12 SIFW 9/13/94- 36 hrs. SITP = 450 PS	I. Dry formation gas bled down in 3	3 min. RU to swab.(continued)
14. I hereby certify that the foregoing is the and correct	Title Regulatory Analyst	Date9/22/94
Signed	Title	Date
Conditions of approval, i any C 20 994	and makingly and willfully to make to any department or agency of th	e United States any false, fictitious or fraudulent statements
Title 18 U.S.C. Section CARPSBADCEN FUNCTION AND A States any Alse, fictitious or fraudulent statements or representations as the for Party States with the Virtual CARP States and the United States any false, fictitious or fraudulent statements *See Instruction on Reverse Side		