		<u> </u>	C.D. COPI	<u>ه</u> سه		し、フィ
Form 9-331 (May 1963)	DEPAR	UNITED STATES		on re-	NM 0556857	NO. 42 R1424. ND SERIAL NO.
cDa not u		DICES AND REPORT	ing back to a different reservol	r.	3. IF INDIAN, ALLOTTEE	
WELL L. 2. SAME OF OPER Mesa Pet 3. Address of O 1000 Vau 4. Location of V See also space At surface	PERATOR John Building	JAN 25 1980 O. C. D. ARTESIA, OFFICE / Midland, Texas 7 n clearly and in accordance with	9701 any State religion State 100 U.S. GEULUGICAL SI ARTESIA, NEW ME	ED θ URVEY	7. UNIT AGREEMENT NAN 8. FARM OR LEASE NAM Nash Unit 9. Well NO. 2 10. FIELD AND POOL, OR Nash Draw Mor 11. Sec. T., R., M., OB BI SUBVEY OR ABEA	wildcat YOW LK. AND
14. PERMIT NO.		15. ELEVATIONS (Show wheth 3057 RKB			Dec 18-235-30E 12. county of parish Eddy	
16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:						
TEST WATER FRACTURE TI SHOOT OR AU ELPAIR WELJ (Other)	EAT	PULL OR ALTER CASING MULTIPLE COMPLETE ABANDON® CHANGE PLANS	(Nor E : Repo Completion o	izing cker Lea rt results o r Recomplet	REPAIRING W ALTERING CA ABANDONMES AKAGE_test f miltiple completion fon Report and Log for conducting estimated dat	SING Tr* X on Well m.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

After potential testing the upper zone (Atoka perfs 12,432'-441') for 4.8 MMCF CAOF in April, 1976, first sales commenced on May 19, 1976. The lower zone (Morrow perfs 13,416'-654') potential tested 11.4 MMCF CAOF in April, 1976, also. First sales from the Morrow zone commenced on May 19, 1976.

A bottom hole pressure survey was run on the Atoka zone in September, 1976, during which the tools were accidently bottomed in the conical shaped short string seal assembly. The lower part of the tool wedged in the seal assembly and attempts to recover same have been unsuccessful. Total production from the Atoka zone was about 190 MMCF. The Atoka zone has been shut in since that time, with only the Morrow zone producing. No additional work is planned until production declines from the Morrow. Also, no additional packer leakage tests are planned.

18. I hereby certify that the forecoing is true and correct SIGNED Michael , William TITLE	Operations Manager	DATE 1-22-80
(This space for Federal or State office use) APPROVED BY CONDITIONS OF APPROVAL, IF ANY:	E	DATE AN S 1931