NM OIL CONS. C	COMMISSION	_	ન
NOVEMBEL 19037 T	8210 U. (ED STATES ARTMENT OF THE INTE	SUEMIT IN TRIFCATE* RIOR verse aide)	Form approved. Budget Bureau No. 1004-0135 Expires August 31, 1985 5. LEASE DESIGNATION AND SERIAL NO.
	UREAU OF LAND MANAGEME	· ·	NM-0415688-A
(Do not use this form for	NOTICES AND REPORTS proposals to drill or to deepen or plu pplication for PERMIT—" for such		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
OIL GAS	· · · · · · · · · · · · · · · · · · ·		7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR 1			8. FARM OR LEASE NAME
3. ADDRESS OF OPERATOR			Old Indian Draw Writ Feeler
P.O. Box 68	4066 nm 8824	O	9. WBLL NO.
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface			10. FIELD AND POOL, OR WILDCAT
1017 FSL X 1973 FWL			11. BEC., T., B., M., OB BLK. AND
. (Sec	.18 Unit N, SE/4 5W/4,)	SURVEY OR ARMA
14. PERMIT NO.	15. ELEVATIONS (Show whether	DF, RT, GR, etc.)	12. COUNTY OR PARISH 13. STATE
	3078' GR		Eddy MM
16. Che	eck Appropriate Box To Indicate	Nature of Notice, Report, or O	ther Data
Managa an announced and a second a second and a second an			SHT REPORT OF:
TEST WATER SHUT-OFF	PCLL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL
FRACTURE TREAT BHOOT OB ACIDIZE	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CASING
REPAIR WELL	CHANGE PLANS	SHOOTING OR ACIDIZING (Other)	ABANDONMENT*
(Other) Water shut	· off	' Completion or Recognible	of multiple completion on Well tion Report and Log form.)
proposed work. If well is nent to this work.) *	TES OFERATIONS (Clearly state all pertin directionally drilled, give subsurface lo	ent details, and give pertinent dates, i cations and measured and true vertical	including estimated date of starting any depths for all markers and zones perti-
opose to inject	solymer in effort:	to permanently see	el water productive
sterval as follow La deference wer		tocke to bang Clar	k 12-21-84.
PO 4 with prod	nction equipment	/	
Perforate 3318-3	324 W/4 DPISPF,	using a 3% Hol	Now Carrier Cop. gun
KIH and DET	apr at 3300.		
OH with phr and	RIH and set conti	retainer at 3300	Sting into retained tagged W/ Iodine 131
sump 2000 gals 1 BLM, C 1-TRB 1-FJA	KTROL X-C Service	and 1000 gals X	TROL V-C Service.
18. I hereby certify that the fores	going is arue and correct	• •	
SIGNED HAM C.		Ast. Admin. Analy	P DATE 12-21-84
(This space for Federal or St	ate office use)	AREA FORMACTO	
APPROVED BY	TITLE	CARLOONU IL LOUIS TO THE	DATE

7. Flush with 19 bbla 200 KCl
8. Sting out of cmf ratainer and POH
9. POH and solutivellin for 24 hrs.
10. Wash, out excess K-Trol to 3300 and clean out to top of
cont. Irdainer.
11. RIH with production equipment, land seating ripple
at 3299'
12. Return well to production.