

ATTACHMENT TO FORM C-101
APPLICATION FOR PERMIT TO DRILL, DEEPEN OR PLUG BACK
NASH UNIT #6
1980' FNL AND 330' FWL
SECTION 18-23S-30E
EDDY COUNTY, NEW MEXICO

3. Drill out plugs as follows:

Plug #1 Surface
Plug #2 205'-1100' Total 895'
Plug #3 1105'-2000' Total 895'
Plug #4 2105'-3000' Total 895'
Drill out CIBP at 3000'
Plug #5 3050'-3200' Total 150'
Intermediate casing shoe at 3112'
Drill out with 7 7/8" bit
Plug #6 4750'-4900' Total 150'

4. Clean out to 5100' TD. Displace with cut brine with 15 cc W.L. and 9.2 NW.
5. Drill to 7400' TD.
6. Run logs and side wall cores. Evaluate.