

BLOWOUT DRILLS

The following is the procedure for pit drills while drilling and tripping pipe.

I. Preparation:

- A. Inside B.O.P.'s
 - 1. See that inside B.O.P.'s are placed on drilling rig floor prior to drilling.
 - 2. Pipe threads will be in good condition, clean and doped.
 - 3. Valve will be clean and not cut.
 - 4. Plunger will be set so that the valve remains open until the inside B.O.P.'s are tightened into the pipe string.
 - 5. The kelly cock safety valve, better known as the "below kelly valve" will be on the kelly all the time and in an open position.
 - 6. Be sure the right wrench is available to fit the cock.
- B. Master Valve, B.O.P.'s, spools, valves, choke manifold, and kill lines.
 - 1. System will be tested once per week.
 - a. B.O.P. 900 series - 2500 psi
 - b. B.O.P. 1500 series - 5000 psi
 - 2. Grease and work all valves once per week and keep plugs in good repair.
 - a. Grease plug valves while open, then close, then leave open. These should be pumped through with mud before each trip to insure no plugging occurs.
 - b. When two valves are used in a line, always use the outside-valve so it can be changed in the event it becomes cut out.
 - 3. Choke sizes will be clearly marked on chokes off choke manifold.
 - 4. Wrenches used to open and close valves on choke manifold will always be on the valves or easily accessible.
 - 5. Ram locking controls will be properly installed on all B.O.P.'s.
 - 6. Use tees with bullplugs rather than ell's in manifolds.
- C. Accumulator tests will be held weekly along with the B.O.P. test.
 - 1. Accumulator pressure will be kept at a minimum of 1500 psi. 700 psi on hydral (to protect rubber).