

Smith ranch road and sign on your left. This latter checkpoint is approximately 0.6 miles before you come to the right hand turn onto the private ranch road mentioned in paragraph (3) above.

- (4) Approximately 1.8 miles after entering the private ranch road, you will pass, on your left, a double-wide mobile home, occupied by Mr. Bill Smith, son of the ranch owner, Mr. W.G. Smith. About 0.1 miles beyond this mobile home you will pass a pump house on your left and, 0.1 miles farther, go through a heavy pipe gate. Approximately 0.9 miles beyond this gate (just before reaching a windmill and cattle watering area) turn to the right onto another ranch road. Continue on this very rough, winding road for approximately 3.6 miles to the wellsite, just to the right of the road, and clearly marked and visible. During this last 3.6 miles, you will pass through two closed, loose-wire gates, the first after about 0.2 miles, and the second after an additional 2.1 miles.
 - (5) An alternate route is available beyond the pump house indicated in the preceding paragraph. This alternate route to the wellsite is shorter than the recommended route by approximately 1.6 miles, but it is a much more difficult route, and it is considered that the dirt work to develop a satisfactory road to the wellsite, via this route, would require considerably more time and expense. However, this route is detailed here for information purposes, although it is recommended that this route not be attempted without a four-wheel drive vehicle. After passing the pump house and the pipe gate, continue without any turnoffs for about 1.0 miles beyond the pipe gate. At that point, you will reach a windmill at the roadside on the right. Turn right through a closed, loose-wire gate and immediately, turn left along the fence (you will be between two parallel fences, about 40 feet apart, used as a corral). Continue on a very rough, winding road, with steep rocky stretches for a distance of approximately 1.2 miles beyond the windmill. At this point, make a sharp right turn through a narrow, loose-wire gate, and continue for approximately 0.7 miles. The location is on the left at this point, very close to the road.
- B. Considerable work will be required to render the recommended existing access roads satisfactory for the passage of the necessary vehicles and equipment. The recommended route detailed in paragraph (4), above, includes approximately 4.6 miles of road which will require bulldozing, blade work, caliche fill in some areas, and a limited amount of blasting. In some areas, the road work should produce the required caliche from the road bed, itself, so that it may not be necessary to obtain additional caliche from a pit. In the latter event, however, caliche will be obtained from an existing caliche pit located on State surface about 1/4 of a mile southwest of the double-wide mobile home occupied by Bill Smith, son of ranch owner W.G. Smith.