

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	/
FILE	/
U.S.G.S.	
LAND OFFICE	
OPERATOR	/

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

RECEIVED

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS APR 19 1978

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- <input type="checkbox"/>		7. Unit Agreement Name	
2. Name of Operator		8. Farm or Lease Name	
C & K Petroleum, Inc. ✓		Carlsbad "7" Com.	
3. Address of Operator		9. Well No.	
P.O. Drawer 3546 Midland, Texas 79702		1	
4. Location of Well		10. Field and Pool, or Wildcat	
UNIT LETTER M, 690 FEET FROM THE West LINE AND 760 FEET FROM		South Carlsbad (Morrow)	
THE South LINE, SECTION 7, TOWNSHIP 22-S, RANGE 27-E N.M.P.M.			
15. Elevation (Show whether DF, RT, GR, etc.)		12. County	
3119 Gr.		Eddy	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	
OTHER <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugged and Abandoned as follows:

March 30, 1978, - Spotted 35' cement on top CIBP @ 11,075'. Shot off 5-1/2" casing @ 10,000', could not free, shot off @ 7,620'. * Pressure to 2000 *
Circ. hole W/9.6 brine gel and lost circ. material. Pulled and layed down 188 jts., 7620', 5-1/2" csg.
Spotted 60 sx. plug over 5-1/2" csg. cut off 7670' - 7570'.
Spotted 60 sx. plug 6909' - 6809'.
Spotted 60 sx. plug 5258' - 5158'.
Spotted 60 sx. plug 3606' - 3509'.
Spotted 60 sx. plug 2660' - 2538'.
Spotted 10 sx. plug @ surface.
Installed dry hole marker. Job completed 4-7-78.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>[Signature]</u>	TITLE <u>Administrative Supervisor</u>	DATE <u>4-18-78</u>
APPROVED BY <u>[Signature]</u>	TITLE <u>OIL AND GAS INSPECTOR</u>	DATE <u>AUG 14 1978</u>
CONDITIONS OF APPROVAL, IF ANY:		