

37. SUMMARY OF POROUS ZONES: (Show all important zones of porosity and contents thereof; cored intervals; and all drill-stem, tests, including depth interval tested, cushion used, time tool open, flowing and shut-in pressures, and recoveries):

FORMATION	TOP	BOTTOM	DESCRIPTION, CONTENTS, ETC.	NAME	TOP	
					MEAS. DEPTH	TRUE VERT. DEPTH
				Delaware	1840	(+1685)
				Bone Spring	5500	(-1975)
				Canyon	10125	(-6600)
				Strawn	10425	(-6900)
				Atoka	10625	(-7100)
				Morrow	11125	(-7600)

38. GEOLOGIC MARKERS