

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

MAR - 7 '90

O. C. D.

WELL API NO.

30-015-22312

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL  
WELL ☒

GAS  
WELL ☐

OTHER

2. Name of Operator

The Eastland Oil Company

3. Address of Operator

P. O. Drawer 3488, Midland, Tx. 79702

4. Well Location

Unit Letter M : 660 Feet From The South Line and 990 Feet From The West Line

Section 29

Township 22S

Range 28E

NMPM Eddy

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3026' GR-3036' DF (ref.)

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

C. R. Lopez "A" #1 was completed 10-30-77 at total depth of 2563' with perforations at 2482'-2500' in Delaware sand. Casing in well is as follows:

8-5/8", 24#, surface casing set @433' with cement circulated.

4½, 9.5#, production casing set @2563' with cement circulated.

Propose to plug as follows:

1. Plug @2500' w/ 25 sx cement & tag.

2. Load hole w/ 9.6# mud thru 2" tubing.

3. Plug @1500' w/ 25 sx cement.

4. Plug @550' w/ 25 sx cement & tag.

5. Plug @surface w/ 10 sx cement.

6. Set 4" x 4" marker in top of casing and prepare location for inspection.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Travis Reed

TITLE Production Superintendent DATE 3-5-90

TYPE OR PRINT NAME Travis Reed

TELEPHONE NO. 683-6293

(This space for State Use)

APPROVED BY

Danell Moore

TITLE

DATE

3/28/90

CONDITIONS OF APPROVAL, IF ANY: