

1600-1500'	100
1000-900	100
650 -550	20 3.5
25-Surface	10

Set 4½" dry hole marker 4' above surface. Pits will be filled and location leveled in near future.