

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on reverse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-6034

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Shearn "D" Federal Com

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Undes. Strawn

11. SEC., T., E., M., OR BLK. AND
SURVEY OR AREA

Sec. 15-T23S-R25E

12. COUNTY OR PARISH

Eddy

13. STATE

NM

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen a well or to plug back a different reservoir.
Use "APPLICATION FOR PERMIT" for such purposes.)

RECEIVED

JUL 5 1979

O. G. C.
ARTESIA, OFFICE1. OIL WELL ☐ GAS WELL ☒ OTHER ☐

2. NAME OF OPERATOR

GULF OIL CORPORATION

3. ADDRESS OF OPERATOR

P.O. Box 670, Hobbs, NM 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

1980' FSL & 1980' FEL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3754' GL

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐

(Other) Plug & Abandon

PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☒CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

11,350' TD.

Pull production equipment. GIH w/CIBP to approx 9000' and cap with a minimum of 35' of cmt. WOC. Test csg to 500 psi. Circ hole w/abandonment mud. Cut csg near free point (approx 8600') & pull. Spot cmt plug from 75' below top of cut 5½" csg to approx 8225' (75' above cut csg top). Spot additional cmt plugs as follows:

- 1) 150' cmt from 6800' to 6950'
- 2) 150' cmt from 5300' to 5450'
- 3) 100' cmt from 3900' to 4000'
- 4) 100' cmt from 2550 to 2700'
- 5) 100' cmt from 550' to 650'

Spot 25' surf plug & install dry hole marker. Clean & clear location.

RECEIVED

JUN 19 1979

U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

N. B. Sikes, Jr.

TITLE Area Engineer

DATE 6-18-79

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE ACTING DISTRICT ENGINEER

DATE JUL 3 - 1979