

Form 9-331
(May 1963)UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPPLICATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.5. LEASE DESIGNATION AND SERIAL NO.
NM-6034 RECEIVED
6. IF INDIAN, ALLOTTEE OR TRIBE NAME

APR 28 1980

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER		7. UNIT AGREEMENT NAME O. C. D.
2. NAME OF OPERATOR GULF OIL CORPORATION		8. FARM OR LEASE NAME Shearn "D" Federal Com
3. ADDRESS OF OPERATOR P.O. Box 670, Hobbs, NM 88240		9. WELL NO. 1
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1980' FSL & 1980' FEL		10. FIELD AND POOL, OR WILDCAT Undes. Strawn
14. PERMIT NO.		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 15-T23S-R25E
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3754' GL		12. COUNTY OR PARISH Eddy
		13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

11,350' TD. 10,105' PB. Set CIBP @ 9000'. Capped w/25 sx cmt (225'). Circ hole w/abandonment mud. Cut csg @ 7603' & pulled. Spotted 158' plug (40 sx cmt) @ 7678' to 7520'. Spotted 45 sx cmt f/6950' to 6800'; 45 sx f/5450'-5300'; 45 sx f/4000'-3850'; 50 sx f/2700'-2550' across 9-5/8" shoe jt. WOC. Tagged cmt plug @ 2658' - spotted 35 sx cmt from 2658' to 2550'. Spotted 45 sx cmt from 650' to 550'. Spot 25' plug @ surf. Install dry hole marker.

Will notify when location is ready for inspection.

Work performed 7-6-79 thru 7-12-79.

RECEIVED

JUL 17 1979

U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED N. S. Sikes, Jr. TITLE Area Engineer DATE 7-16-79

(This space for Federal or State office use)

(Orig. Sgd.) GEORGE H. STEWART

APPROVED BY _____ TITLE _____ DATE APR 28 1980

CONDITIONS OF APPROVAL, IF ANY: