

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

MAR 4 1994

WELL API NO. 50-015-22441
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name CITY OF CARLSBAD
8. Well No. 1
9. Pool name or Wildcat HERRADURA BEND CHERRY CANYON
10. Elevation (Show whether DF, RKB, RT, GR, etc.)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator
THE EASTLAND OIL COMPANY

3. Address of Operator
P. O. DRAWER 3488, MIDLAND, TX 79702

4. Well Location
Unit Letter K : 2110 Feet From The SOUTH Line and 1980 Feet From The WEST Line
Section 29 Township 22-S Range 28E NMPM EDDY County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2/8/94 Circulated hole with mud, spot 25 sx, plug w/2% CACL at 3286'. Pulled 10 stands, let set 3 hrs. TIH. Tagged plug @3010'. Lay tbgs to 2461'. Circulated hole w/mud, pumped 30 sx, plug 2461'-2034'. Lay down tbgs to 463'. Broke circulation, pumped 25 sx, plug w/2% CACL. Pulled 10 stands. Let set 2½ hrs. TIH to tag plug, no tag. Broke circulation with mud & circulated out plug. Pumped 15 sx, plug w/2% CACL @463'. TOH & SDFD.

2/9/94 TIH, tagged plug @245', TOH. Remove BOP & wellhead, ran 1 jt. tbgs. Pumped 10 sx plug for surface plug. Cut off pipe, install 4' x 4" dry hole marker.

Part I.D. 2
2-10-94
RFR

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Travis Reed TITLE PRODUCTION SUPERINTENDENT DATE 3/2/94

TYPE OR PRINT NAME TRAVIS REED TELEPHONE NO. 915/683-6293

(This space for State Use)

APPROVED BY Karl Eisen TITLE FCI DATE 11-28-15

CONDITIONS OF APPROVAL, IF ANY: