OF COPIES HE	CEIVED .			Form C+403						
DISTRIBUT	ION	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	CEIVED	Supersedes Old						
AFE	7	1	SERVATION COMMISSION	C-102 and C-103						
				Effective 1-4-65						
		-{ Fi	EB 1 9 1979	Sa Indicate Type of Locate						
MD OFFICE										
CRATOR	1		<u> </u>	5, State Cil & Gas Lease No.						
		AR	TEBIA, OFFICE	L-711						
	SUMDE	RY NOTICES AND REPORTS ON	WELLS	MILLINITINI TO THE TOTAL TO THE T						
U 104 00.	SE THIS FORM FOR PRI	CT INDITICES AND REPORTS ON TO ONE OR PEUG FED OR PEUG FORM CAUSE FOR PERMIT HE FORM CALOID FOR SUC	BACK TO A DIFFERENT RESERVOIR.							
	OSE TAPPLICAT	TOWN COLUMN TOWN	The Paris Care Care Care Care Care Care Care Care	7. Unit Agreement Hame						
	SAS X			, ,						
1.6.6		OTHER-								
in e of Cperato	or		•	8. Flum or Lease Dame						
Harvey E	. Yates Comp	any		Amoco 22 State						
Address of Open	rator			9, Well No.						
P. O. Box 1933, Roswell, N. M. 88201				1						
Proximity Well				18. Field and Pool, or Wildcat						
	77	1000 Namel	(()	Und C. Canlabal Manage						
. HIT LETTER _	E	1980 FEET FROM THE North	LINE AND OOU FEET FRO	Und. S. Carlsbad Morror						
₁⊑ <u>√les</u>	t LINE, SECTI	ion 22 township 23S	RANGE 27E NMF							
				$\Delta IIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII$						
		15. Elevation (Show whether	DF, RT, GR, etc.)	12. County						
		3148.6'	GL	Eddy						
لللللللن	.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	· · · · · · · · · · · · · · · · · · ·								
	Check	Appropriate Box To Indicate 1	Nature of Notice, Report or O	ther Data						
	NOTICE OF I	NTENTION TO:	SUBSEQUEN	NT REPORT OF:						
ORM REMEDIA	LWORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING						
ORARILY ABAI	7		COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT						
	7	CHANGE PLANS	CASING TEST AND CEMENT JOB	TOO AND ABANDONMENT						
DP ALTER CA	21HC	LHANGE PLANS		Rig, Run Intermediate XX						
HER			casing, cement,	test etc.						
	and or Completed C	Propositions (Ciently state all pertinent des	tails and nive pertinant dates includi	ng estimated date of starting any proposed						
TAJ SEE RU		pelations (citary state an periment and	rais, and give periment dutes, include	ng estimated date of starting dity proposed						
1-4-79	Drilled to	a TD of 1980'. Move off	cable tool rig.							
1-18-79	Move in Rot		-							
1-24-79 Finish RU. Begin drilling at 9:00 pm. 1-13-79 Ran 5591' (140 Jts) 8 5/8" OD K-55 32# (4500.59') and 24# (1091.41') set at 5606' KB and cemented as follows:										
						<u>lst stage:</u>				
						780 Sx HLW w/8# salt/sx, 1/4# flocele and 200 sx H Neat. PD @ 1:45 am 2-14-79. Dropped opening bomb and opened DV tool at 1990' KB. Circulated				
		cement.	•							
	33 UX	cemetre.								
	0 1 .									
	2nd stage:	1-11								
		Sx HLW $w/8\#$ salt/sx, $1/4\#$		te/sx and 100 sx						
H Neat. PD @ 8:30 am. Circulated 50 Sx.										
	WOC 18 hours									
Test DV collar and casing with 1800# for 2 3/4 Hrs. OK.										
rest by corrar and casting with root in 2 3/4 ins. UK.										
hereby certif	ry that the informatio	shove is true and complete to the best	or my knowledge and belief.							
/ /	Y17_L	na la								
	eck / Th	resset "	Engineer	2-19-79						
	n. 1.									
	110 21	resset	SUPERVISOR, DISTRICT II	FEB 1 9 1979						