DISTRIBUTION					$\neg u \land J \land i$	
		NEW MEXICO OIL CON	SERVATION COMMI	۰ ۱	Form C-101	5-2245
SANTA FE	14	MAR -	8 1978		Revised 1-1-6	5
FILE	10		1010		SA. Indicute	Type of Loane
U.S.G.S.	2		· ····		STATE	PEE [X
LAND OFFICE		0.0			5. State Oil	& Gas Lease No.
OPERATOR		ARTERIA	e OFFilia			
	- <u>t-;</u> 1				huun	
APPLICA	TION FOR P	ERMIT TO DRILL, DEEPEN	I, OR PLUG BACK			
1a. Type of Work					7. Unit Agree	ament Narve 777777777777777777777777777777777777
DRILL		DEEPEN	Di via a			
b. Type of Well	1	DEEPEN	PLUGE	заск	8. Farm or L	ease Mame
OIL GAS WELL	X 。	THER	SINGLE MUL	ZONE	Pardue	Farms Gas C
2. Name of Operator				ZONE	9. Well No.	
Amoco Productio	n Company				1	
3. Address of Operator		· · · · · · · · · · · · · · · · · · ·	***		10. Fjeld Jun	Port or Willbut
P. O. Drawer A,	Levellan	d, Texas 79336				ignated-Morr
4. Location of Well	G	LOCATED 1980	Nor	th LINE		
UNITL	ETTER	LOCATED	FEET FROM THE NOT	LINE	()))))))	
AND 1980 FEET F	Eas	t LINE OF SEC. 26	TWP. 23-5 RGE. 28-		$\forall IIIIII$	///////////////////////////////////////
		LINE OF SEC.	TWP. 200 RCE. 20	- NMPM	12. County	milli
HHHIIIHHH	////////	///////////////////////////////////////	///////////////////////////////////////	IIIII	Eddy	
****	HHHH	+++++++++++++++++++++++++++++++++++++++		++++++	trann	4444
	MMM			())))))		HHHHHH
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	44444			711111	111111	MANIN
	HHHH			9A. Formation Mannau	n	20. Interry or C.T.
MIMM	<u>illilli</u>		13,300	Morrow		Rotary
21. Elevations (Show whether 3012.4 GR	Dr, KI, etc.)	21A. Kind & Status Plug. Bend Blanket-On File	213. Drilling Contractor			Date Work will sta
		Dialiket-on File			FiarCi	h 10, 1978
23.		PROPOSED CASING A	ND CEMENT PROGRAM			
SIZE OF HOLE				<u>.</u>		• • • • • • • • • • • • • • • • • • •
20"	16"	F CASING WEIGHT PER FO	OT SETTING DEPTH	Circul		EST. TOP
	1 10	00#	400	1 1 1 1 1 1 1 1 1	ate	
+		3/01		- 1		
14-3/4"	- 10-	3/4" 51#	3,000'	Circul	1	27711
9-1/2"	-10-	5/8" 29.7#, 33.7#	3,000' 11,370'	Circul Tie-Ba	ick to 10	
14-3/4" 9-1/2" 6-1/2"	-10- 7- 5" ill and e	578" 29.7#, 33.7# 18# quip. Morrow well at	3,000' 11,370' 11,000 to 13,30	Circul Tie-Ba 00' Tie-	ick to 10 Back to	
14-3/4" 9-1/2" 6-1/2" Propose to dr	-10- 7- 5" ill and e ng as nec 0' 400' 3,000'	578" 29.7#, 33.7# 18# quip. Morrow well at essary. - 400' - Native mu - 3,000' - Native mu - 11,370' - Brine wat maintain - 13,300' - Cut brine	3,000' 11,370' 11,000 to 13,30 13,300'. Attempt d and fresh water d and brine water er and low solid good hole conditio	Circul Tie-Ba 00' Tie- completi non-disp ons. L water	ersed mu	7-5/8" casin rforating d to ient mud
9-1/2" 9-1/2" 6-1/2" Propose to dr and stimulati	-10- 7- 5" ill and e ng as nec 0' 400' 3,000'	578" 29.7#, 33.7# 18# quip. Morrow well at essary. - 400' - Native mu - 3,000' - Native mu - 11,370' - Brine wat maintain - 13,300' - Cut brine	3,000' 11,370' 11,000 to 13,3 13,300'. Attempt d and fresh water d and brine water er and low solid good hole condition water and add KC	Circul Tie-Ba 00' Tie- completi non-disp ons. L water itions.	ersed mu APPROVA	7-5/8" casin rforating d to ient mud
9-1/2" 9-1/2" 6-1/2" Propose to dr and stimulati	-10- 7- 5" ill and e ng as nec 0' 400' 3,000'	578" 29.7#, 33.7# 18# quip. Morrow well at essary. - 400' - Native mu - 3,000' - Native mu - 11,370' - Brine wat maintain - 13,300' - Cut brine	3,000' 11,370' 11,000 to 13,3 13,300'. Attempt d and fresh water d and brine water er and low solid good hole condition water and add KC	Circul Tie-Ba 00' Tie- completi non-disp ons. L water itions.	on by per on by per oersed mu w/suffic APPROVAN	7-5/8" casin rforating d to ient mud L VALID G UNICESS
14-3/4" 9-1/2" 6-1/2" Propose to dr and stimulati Mud Program:	-10- 7- 5" ill and e ng as nec 0' 400' 3,000' 11,370'	578" 29.7#, 33.7# 18# quip. Morrow well at essary. - 400' - Native mu - 3,000' - Native mu - 11,370' - Brine wat maintain - 13,300' - Cut brine	3,000' 11,370' 11,000 to 13,3 13,300'. Attempt d and fresh water d and brine water er and low solid good hole condition water and add KC	Circul Tie-Ba 00' Tie- completi completi non-disp ons. L water itions.	ersed mu w/suffic APPROVAN FOR 93 D/AY RELEVO CC	7-5/8" casin rforating d to ient mud L VALID G UNIESS GANCESS
14-3/4" 9-1/2" 6-1/2" Propose to dr and stimulati Mud Program: BOP Program a	-10- 7- 5" ill and e ng as nec 0' 400' 3,000' 11,370' ttached.	578" 29.7#, 33.7# 18# quip. Morrow well at essary. - 400' - Native mu - 3,000' - Native mu - 11,370' - Brine wat maintain - 13,300' - Cut brine	3,000' 11,370' 11,000 to 13,3 13,300'. Attempt d and fresh water d and brine water er and low solid good hole condition water and add KC	Circul Tie-Ba 00' Tie- completi completi non-disp ons. L water itions.	ersed mu w/suffic APPROVAN FOR 93 D/AY RELEVO CC	7-5/8" casin rforating d to ient mud L VALID G UNCESS
14-3/4" 9-1/2" 6-1/2" Propose to dr and stimulati Mud Program:	-10- 7- 5" ill and e ng as nec 0' 400' 3,000' 11,370' ttached.	578" 29.7#, 33.7# 18# quip. Morrow well at essary. - 400' - Native mu - 3,000' - Native mu - 11,370' - Brine wat maintain - 13,300' - Cut brine	3,000' 11,370' 11,000 to 13,3 13,300'. Attempt d and fresh water d and brine water er and low solid good hole condition water and add KC	Circul Tie-Ba 00' Tie- completi completi non-disp ons. L water itions.	ersed mu w/suffic APPROVAN FOR 93 D/AY RELEVO CC	7-5/8" casin rforating d to ient mud L VALID G UNIESS GANGEOS
14-3/4" 9-1/2" 6-1/2" Propose to dr and stimulati Mud Program: BOP Program a Gas is not co	-10- 7- 5" ill and e ng as nec 0' 400' 3,000' 11,370' ttached. mmitted.	578" 29.7#, 33.7# 18# quip. Morrow well at essary. - 400' - Native mu - 3,000' - Native mu - 11,370' - Brine wat maintain - 13,300' - Cut brine to mainta	3,000' 11,370' 11,000 to 13,30 13,300'. Attempt d and fresh water d and brine water er and low solid good hole conditi water and add KC in good hole cond	Circul Tie-Ba 00' Tie- completi non-disp ons. L water itions. <i>H</i> <i>D</i>	ersed mu w/suffic APPROVAL FOR SO DAY RELEVO CC	7-5/8" casin rforating d to ient mud L VALID U UNIEDS CLASS NEED, -78
14-3/4" 9-1/2" 6-1/2" Propose to dr and stimulati Mud Program: BOP Program a Gas is not co	-10- 7- 5" ill and e ng as nec 0' 400' 3,000' 11,370' ttached. mmitted.	578" 29.7#, 33.7# 18# quip. Morrow well at essary. - 400' - Native mu - 3,000' - Native mu - 11,370' - Brine wat maintain - 13,300' - Cut brine to mainta	3,000' 11,370' 11,000 to 13,30 13,300'. Attempt d and fresh water d and brine water er and low solid good hole condition water and add KC in good hole cond	Circul Tie-Ba 00' Tie- completi non-disp ons. L water itions. <i>H</i> <i>D</i>	ersed mu w/suffic APPROVAL FOR SO DAY RELEVO CC	7-5/8" casin rforating d to ient mud L VALID U UNIESS SUMENCES, 2-78
14-3/4" 9-1/2" 6-1/2" Propose to dr and stimulati Mud Program: BOP Program a Gas is not co	-10- 7- 5" ill and e ng as nec 0' 400' 3,000' 11,370' ttached. mmitted.	578" 29.7#, 33.7# 18# quip. Morrow well at essary. - 400' - Native mu - 3,000' - Native mu - 11,370' - Brine wat maintain - 13,300' - Cut brine to mainta	3,000' 11,370' 11,000 to 13,30 13,300'. Attempt d and fresh water d and brine water er and low solid good hole condition water and add KC in good hole cond	Circul Tie-Ba 00' Tie- completi non-disp ons. L water itions. <i>H</i> <i>D</i>	ersed mu w/suffic APPROVAL FOR SO DAY RELEVO CC	7-5/8" casin rforating d to ient mud L VALID U UNIESS SUMENCES, 2-78
14-3/4" 9-1/2" 6-1/2" Propose to dr and stimulati Mud Program: BOP Program a Gas is not co	-10- 7- 5" ill and e ng as nec 0' 400' 3,000' 11,370' ttached. mmitted.	578" 29.7#, 33.7# 18# quip. Morrow well at essary. - 400' - Native mu - 3,000' - Native mu - 11,370' - Brine wat maintain - 13,300' - Cut brine to mainta ROGRAM: IF PROPOSAL IS TO DECEPT	3,000' 11,370' 11,000 to 13,30 13,300'. Attempt d and fresh water d and brine water er and low solid good hole condition water and add KC in good hole cond * OR PLUG BACK, GIVE DATA ON	Circul Tie-Ba 00' Tie- completi completi non-disp ons. L water itions. <i>F</i> <i>D</i> <i>EXPIRE</i>	on by per on by per oersed mut w/suffic APPROVAL FOR GO DAY BILLING CC SS 6-13 SDUCTIVE ZONE	7-5/8" casin rforating d to ient mud L VALID U UNIESS SUMENCED, -78
14-3/4" 9-1/2" 6-1/2" Propose to dr and stimulati Mud Program: BOP Program a Gas is not co N ABOVE SPACE DESCRIBE IVE ZONE. CIVE BLOWOUT PREV hereby certify that the inform	-10- 7- 5" ill and e ng as nec 0' 400' 3,000' 11,370' ttached. PROPOSED P ENTER PROGRAM	578" 29.7#, 33.7# 18# quip. Morrow well at essary. - 400' - Native mu - 3,000' - Native mu - 11,370' - Brine wat maintain - 13,300' - Cut brine to mainta ROGRAM: IF PROPOSAL IS TO DECEPT	3,000' 11,370' 11,000 to 13,30 13,300'. Attempt d and fresh water d and brine water er and low solid good hole condition water and add KC in good hole cond	Circul Tie-Ba 00' Tie- completi completi non-disp ons. L water itions. <i>F</i> <i>D</i> <i>EXPIRE</i>	on by per on by per oersed mut w/suffic APPROVAL FOR GO DAY BILLING CC SS 6-13 SDUCTIVE ZONE	7-5/8" casin rforating d to ient mud L VALID D UNIERS DIVE NCEED, -28
14-3/4" 9-1/2" 6-1/2" Propose to dr and stimulati Mud Program: BOP Program a Gas is not co N ABOVE SPACE DESCRIBE IVE ZONE. CIVE BLOWOUT PREV hereby certify that the inform	-10- 7- 5" ill and e ng as nec 0' 400' 3,000' 11,370' ttached. mmitted.	578" 29.7#, 33.7# 18# quip. Morrow well at essary. - 400' - Native mu - 3,000' - Native mu - 11,370' - Brine wat maintain - 13,300' - Cut brine to mainta ROGRAM: IF PROPOSAL IS TO DECEPT	3,000' 11,370' 11,000 to 13,30 13,300'. Attempt d and fresh water d and brine water er and low solid good hole condition water and add KC in good hole cond * OR PLUG BACK, GIVE DATA ON	Circul Tie-Ba 00' Tie- completi completi non-disp ons. L water itions. <i>F</i> <i>D</i> <i>EXPIRE</i>	on by per on by per oersed mut w/suffic APPROVAL FOR GO DAY BILLING CC SS 6-13 SDUCTIVE ZONE	7-5/8" casin rforating d to ient mud L VALID D UNIERS DIVE NCEED, -28
14-3/4" 9-1/2" 6-1/2" Propose to dr and stimulati Mud Program: BOP Program a Gas is not co N ABOVE SPACE DESCRIBE IVE ZONE. CIVE BLOWOUT PREV hereby certify that the inform	-10- 7- 5" ill and e ng as nec 0' 400' 3,000' 11,370' ttached. PROPOSED P ENTER PROGRAM	578" 29.7#, 33.7# 18# quip. Morrow well at essary. - 400' - Native mu - 3,000' - Native mu - 11,370' - Brine wat maintain - 13,300' - Cut brine to mainta ROGRAM: IF PROPOSAL IS TO DEEPER . IF ANY. true and complete to the best of my 	3,000' 11,370' 11,000 to 13,30 13,300'. Attempt d and fresh water d and brine water er and low solid good hole condition water and add KC in good hole cond knpwledge and bellef. inistrative Super	Circul Tie-Ba 00' Tie- completi non-disp ons. L water itions. <i>F</i> <i>D</i> <i>EXFIRE</i> PRESENT PRO	Date	7-5/8" casin rforating d to ient mud L VALID D UNIEDS DUMEDS DUMEDS DUMEDS DATE NOLDS AND PROPOSED NEW F
14-3/4" 9-1/2" 6-1/2" Propose to dr and stimulati Mud Program: BOP Program a Gas is not co N ABOVE SPACE DESCRIBE IVE ZONE. CIVE BLOWOUT PREV hereby certify that the inform	-10- 7- 5" ill and e ng as nec 0' 400' 3,000' 11,370' ttached. PROPOSED P ENTER PROGRAM	578" 29.7#, 33.7# 18# quip. Morrow well at essary. - 400' - Native mu - 3,000' - Native mu - 11,370' - Brine wat maintain - 13,300' - Cut brine to mainta ROGRAM: IF PROPOSAL IS TO DEEPER . IF ANY. true and complete to the best of my 	3,000' 11,370' 11,000 to 13,30 13,300'. Attempt d and fresh water d and brine water er and low solid good hole condition water and add KC in good hole cond * OR PLUG BACK, GIVE DATA ON	Circul Tie-Ba 00' Tie- completi non-disp ons. L water itions. <i>F</i> <i>D</i> <i>EXFIRE</i> PRESENT PRO	Date	7-5/8" casin rforating d to ient mud L VALID D UNIERS DIVE NCEED, -28
14-3/4" 9-1/2" 6-1/2" Propose to dr and stimulati Mud Program: BOP Program a Gas is not co NABOVE SPACE DESCRIBE NE 20NE. CIVE BLOWOUT PREV hereby certify that the inform igned	-10- 7- 5" ill and e ng as nec 0' 400' 3,000' 11,370' ttached. mmitted. PROPOSED P ENTER PROGRAM Nation Above Is W. (or State Use)	578" 29.7#, 33.7# 18# quip. Morrow well at essary. - 400' - Native mu - 3,000' - Native mu - 11,370' - Brine wat maintain - 13,300' - Cut brine to mainta ROGRAM: IF PROPOSAL IS TO DEEPER . IF ANY. true and complete to the best of my 	3,000' 11,370' 11,000 to 13,30 13,300'. Attempt d and fresh water d and brine water er and low solid good hole condition water and add KC in good hole cond knpwledge and bellef. inistrative Super	Circul Tie-Ba 00' Tie- completi non-disp ons. L water itions. <i>F</i> <i>D</i> <i>EXFIRE</i> PRESENT PRO	Date	7-5/8" casin rforating d to ient mud L VALID D UNIEDS DUMEDS DUMEDS DUMEDS DATE NOLDS AND PROPOSED NEW F

· .