

PARDUE FARMS GAS COM NO. 1
RECOMPLETE TO THE MORROW AND DUAL WITH THE ATOKA
EDDY COUNTY, NEW MEXICO

1. RUSU X KILL ATOKA ZONE X POH W/ PROD EQUIP.
2. RIH X WASH OVER GUIBERSON RBP-6 LEFT IN HOLE. TOP OF FISH AT 11875'.
(ON PREVIOUS WORKOVERS TO STIMULATE THE ATOKA, HAD PROBLEMS GETTING
IN 5" LINER AT 11066'. MAY NEED TO DRESS WITH MILL). POH W/ RBP.
3. CLEAN OUT TO PBTD OF 13266' OR BELOW 13000'
4. RIH W/ PKR X PRESSURE TEST CASING.
5. RIH W/ TBG X SLIDING SLEEVE X ON/OFF TOOL X PKR X SEATING NIPPLE.
SET PKR AT APPROXIMATELY 12,300' (BOTTOM ATOKA PERF AT 11,798').
6. LOAD BACKSIDE AND SWAB DOWN TUBING TO APPROXIMATELY 8000'.
7. PERFORATE THE INTERVAL 12.958'-12.970 IN THE 5" LINER AT 4 JSPF
THRU TUBING GUN. CORRELATE TO
SCHLUMBERGER OPEN HOLE CNL-FDC LOG DATED 6-10-78.
8. SWAB TO TEST.
9. IF INTERVAL SWABS DRY, ACIDIZE WITH 1000 GALS MS ACID. FLUSH WITH TBG
VOLUME OF 2% KCL WATER.
10. SWAB TO TEST.