

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-71

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.G.S.	<input checked="" type="checkbox"/>
LAND OFFICE	<input checked="" type="checkbox"/>
OPERATOR	<input checked="" type="checkbox"/>

5a. Indicate Type of Lease  
State ☐ Fee ☒  
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT ZONE. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

RECEIVED

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Lanexco, Inc.	8. Farm or Lease Name Cerro Com
3. Address of Operator P.O. Box 1206 Jal, N.M. 88252	9. Well No. 1
4. Location of Well UNIT LETTER <u>E</u> <u>2080</u> FEET FROM THE <u>NORTH</u> LINE AND <u>760</u> FEET FROM THE <u>WEST</u> LINE, SECTION <u>11</u> TOWNSHIP <u>23-S</u> RANGE <u>27-E</u> NMPM.	10. Field and Pool, or Wildcat Cass Draw Wolfcamp
15. Elevation (Show whether DF, RT, GR, etc.) 3092.4 GL	12. County Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <u>Recomplete as a dual producer</u> <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5-16-88 Set a BFC blanking plug in On-Off tool on Lok Set packer at 9685' to isolate Wolfcamp zone while attempting to complete Bone Springs above.

5-31-88 Fished BFC blanking plug from top of tool. This zone had 2500 P.S.I. Start the Wolfcamp zone producing.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Mike Coguland TITLE Production Supt. DATE July 12, 1988

Original Signed By  
Mike Williams

DATE JUL 22 1988

CONDITIONS OF APPROVAL, IF ANY: