STATE OF NEW MEXICO	•
ENERGY AND MINERALS DEPARTMENT	
OIL CONSERVATION DIVISION	
DISTRIBUTION P. O. BOX 2088	Form C-103 Revised 10-1-7
SANTA PE V SANTA FE, NEW MEXICO 87501	Revised 10-1-7
	5a, Indicate Type of Lease
U.S.O.S. RECEIVED	
	State Fee X
OPERATOR	5, State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS JUL 15 '88	
SUNDRY NOTICES AND REPORTS ON WELLS JUL 12 00	
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALE.)	
	7. Unit Agreement Name
ARICER, ARITAL	
2. Name of Operator	8, Farm or Lease Name
Lanexco, Inc. \checkmark	Cerro Com
3. Address of Operator	9. Well No.
P.O. Box 1206, Jal N.M. 88252	_
4. Location of Well	1
	10, Field and Pool, or Wildcat
UNIT LETTER E 2080 FEET FROM THE NORTH LINE AND 760 FEET FROM	Wildeat Bone. Sprin
UNIT LETTER FEET PROM THE TOTALITE LINE AND FEET PROM	
THE WEST LINE, SECTION 11 TOWNSHIP 23-S RANGE 27-E	
THE LINE, SECTION TOWNSHIP RANGE MMPM.	
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
3092.4 GL	Eddy
16. Check Appropriate Par To Indiana Name (Maria Para)	
Check Appropriate Box To Indicate Nature of Notice, Report or Oth	er Data
NOTICE OF INTENTION TO: SUBSEQUENT	REPORT OF:
PERFORM REMEDIAL WORK	ALTERING CABING
TEMPORARILY ABANDON	
	PLUS AND ABANDOHMENT
OTHER <u>Recomplete as c</u>	lual producer X
отига	
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including e	
work) SEE RULE 1003. (WORK composed on March 1000)	stimated date of starting any proposed
Sale and the second a	
5-16-88 Set BFC blanking plug in Lok Set packer at 9685	ft. Blow well down.
5-1/-88 Tally tubing from hole. Perforate 34 holes from	7404-7425, 5-18-88
Run treating tools testing tubing to 8000PSI. Packer fai	led. 5-19-88 Trin
tools for repairs. Test tools-held. Acidize with 4,000 g	al 15% NF-FF and
68 RCN ball sealers. 5-20-22 Swab well with good show of	
well with 15 000 gal Col 20% CO2 werd attrack good show of	011. 5-23-33 Frac
well with 15,000 gal. Gel 30% CO2, and 345 sacks 20-40 s	and. Left shut in
2 hours and flowed back on controlled choke. 5-24-88 Swa	b with show of oil.
5-25-88 Pull treating tools from hole. 5-26-88 Install d	ual tubinghead
run Un&UII tool and sting back onto packer. 5-27-88 Run	227 jointe 2 3/8"
tubing and land at 7394.80 ft. Could not fish blanking p	5 - 30 - 88 - 811
227 jts. tubing. Got off Lok-Set and circulated back ove	m and store hash
onto Lok-Set 5-31 Pup 227 joints hack in a line of the	r, and stung back
onto Lok-Set. 5-31 Run 227 joints back in and landed. Ri	g up dual tree.
Fish blanking plug from hole. Rig down unit. 6-1-88 Rig	up swabbing unit
and swap through 6-15-88, recovering 500 bbls. oil and 6	00 bbls, water.
6-16-88 Rig up plunger lift system and test through 6-18	-88. Rig swab
unit down in preparation to run downhole pump. 6-21-88 M	Ove an American
228 pumping unit to location, and install.6-22-88 Rig pul	ling unit un and
run 294 rods, and 2x12x201 nump Hang on and laft derived	ing unic up and
run 294 rods, and 2x11x20' pump. Hang on and left down i	n preparation for
electrifying. 6-23 through 7-11 Awaiting SPS for electri	flcation.
8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
V	
Inte Mike Copeland Troduction Supt.	July 12, 1988
IENER Mike Copelond TITLE Production Supt.	DATE July 12, 1988
	DATE July 12, 1988
Original Signed By	
	DATE JULY 12, 1988
Original Signed By	

.