

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.O.S.	
LAND OFFICE	
OPERATOR	<input checked="" type="checkbox"/>

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

RECEIVED

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS OF WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL <input type="checkbox"/> GAS <input type="checkbox"/> OTHER- Dry-hole		7. Unit Agreement Name
2. Name of Operator Enron Oil & Gas Company		8. Farm or Lease Name Teledyne 4 Com.
3. Address of Operator P. O. Box 2267, Midland, Texas 79702		9. Well No. 1
4. Location of Well UNIT LETTER P, 660 FEET FROM THE south LINE AND 330 FEET FROM THE east LINE, SECTION 4 TOWNSHIP 23S RANGE 29E N.M.P.M.		10. Field and Pool, or Wildcat Wildcat Atoka
15. Elevation (Show whether DF, RT, GR, etc.) 2952.3' GR		12. County Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐  
TEMPORARILY ABANDON ☐  
PULL OR ALTER CASING ☐  
OTHER ☐

PLUG AND ABANDON ☒  
CHANGE PLANS ☐  
OTHER ☐

REMEDIAL WORK ☐  
COMMENCE DRILLING OPNS. ☐  
CASING TEST AND CEMENT JOBS ☐  
OTHER ☐

ALTERING CASING ☐  
PLUG AND ABANDONMENT ☐  
OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Spot 20 sacks Class H from 11,940 to 11,740 feet.
2. Spot 50 sacks Class H from 11,250 to 11,050 feet.
3. Spot 50 sacks Class H from 6000. to 5800 feet.
4. Spot 150 sacks Class H from 3000 to 2400 feet, and tag cement.
5. Spot 150 sacks Class H from 2400 to 1800 feet, and tag cement.
6. Spot 150 sacks Class H from 1800 to 1200 feet.
7. Spot 150 sacks Class H from 1200 to 600 feet.
8. Spot 150 sacks Class H from 600' to surface.
9. Cut off wellhead; install dry-hole marker.

Notify N.M.O.C.C. in sufficient time to witness

Plugging

Post ID-2  
9-16-88  
P+ A

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Betty Gildon Betty Gildon TITLE Regulatory Analyst DATE 9/6/88

APPROVED BY Mike Williams TITLE  DATE SEP 12 1988

CONDITIONS OF APPROVAL, IF ANY: