. U. OF COMIES PECCIVED					-5	Form C-101 Supersoles Old	
DISTRIBUTION	3					C-102 and C-103	
HTAFE	1	н	EM MEXICO OIL CORS				
i.C					EIVED		
5.G.S.							
OID OFFICE		1		AAAD	9 n 1070		
HOTALL	\Box			MAK	00 1373	5. State Off & Gua Lease No.	
						Survey and the survey of the	
	SUN	DRY ROTICES	S AND DEPORTS ON				
(DO NOT USE THIS FO	1 4 6 4 6 1	CATION FOR PERMIT	C To thouse Colors to the form	4 PACPUSALS.	Ship of Pica	WILLIAM TO THE STATE OF THE STA	
						7. Onte represent rease	
WILL WILL	NEW MEXICO OIL CONSERVATION COMMISSION						
NEW MEXICO OIL CONSERVATION COMMISSION TO SUPPLIE AC.S. MAR 3 0 1979 MAR 3 0 1979 MAR 3 0 1979 SUPPLIES AND SEFORTS ON WELLS J. C. Barnes Oil Company J. C. Barnes Oil Company Post Office Box 505 Midland, Texas 79702 MIDDING OF OPPOSITE East 1 1980 FORT FROM THE SUPPLIES AND SEFTION TO TO SUPPLIES AND SEFORTS ON WELLS ACTION OF THE MALE AND ADDRESS OF THE SUPPLIES AND SEFTION Check Appropriate Box To Indicate Nature of Notice, Report of Notice of Intention To: SUBSEQ CHARLEST AND CHARLES AND CHARLE						1	
	Barr	nes Uil Comp	pany /				
these of Operator	occ:	• Dev COC	Widland Toxas	70702		7	
Post	OITIC	ce BOX 505	Midiand, Texas	-3702		10 Field and Fool, or Valded	
coutton of Well		• 000	C 4 h		1000		
UNIT LETTER		1980	T FROM THE	LINE AND	1900 FEET FROM	VIIII MOLLOW	
East	LINE, SE	CTION	TOWNSHIP		NMPH.		
	~~~	· · · · · · · · · · · · · · · · · · ·		INC BT CD		13 Co. 012	
		(////// :3.			•		
<u> </u>	77777	7/////				1	
	Chec	k Appropriate	: Box To Indicate N	lature of Notic	ce, Report or Ot	lier Data	
NOTIC	CE OF	INTENTION	TO:	<b>{</b>	SUBSEQUEN.	FREPORT OF:	
				•	<b>6</b> 7		
FORM REMEDIAL WORK	]		PLUG AND ABANDON	REMEDIAL WORK	닏		
IPCHARILY ABAHDON	]			_	673	PLUG AND ABANDONMENT	
L OR ALTER CASING	]		CHANGE PLANS	CASING TEST AND	CEMENT JOB XX		
				OTHER			
DIHER							
L. C.		Clea	uly state all pertinent det	ails, and rive perti	inent dates, including	estimated date of starting any proposed	
WORK SEE RULE 1103.	minered						
	-			200 ex			
						1 0/0 0111 -	
						1 3/24/79	
			7				
Temp. Survey-Top of cement or						cement outside	
						g @ 9200'.	
					_,		
around slips,	comin	g from annu	llus between 5 1/ mifold. NOW. DO	2 & 7 5/8 ca NOT HAVE GO	ising. Set be OOD CEMENT JOI	B ON 5 1/2 CASING. Kill	
		•					
After completi	ng th	e cementing	, casing will be	tested and	turned into 1	the Commission before	
well completion	n is	started.					
thereby centily that the	informat	ion above is true	and complete to the best	of my knowledge at	na penet.		
× /-	W.	10 (10	_,	110		March 20 1070	
· / * / /	//	LERC-	CC virue Fie	Id Supt.		DAYE MATCH 29, 19/9	
- ATE TO A STATE OF THE A	2×242		e mark victor el consense de l'altre de	*************	<u> </u>		
110	د ا	4 -	-	atinepi/ICOP	DISTRICT II	APR 2 1979	
(1) (1.	X	tresser	11116	SUPERVISOR,	DISTRICT T	APR 2 1979	