

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.G.S.	
LAND OFFICE	
OPERATOR	<input checked="" type="checkbox"/>

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501
RECEIVED BY
JUL 25 1985
O. C. D.
ARTESIA, OFFICE

Form C-103
Revised 10-1-78

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL <input type="checkbox"/> GAS <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Maddox Energy Corporation	8. Farm or Lease Name Malaga
3. Address of Operator 1008 W. Pierce, Suite 2-A, Carlsbad, New Mexico 88220	9. Well No. 1
4. Location of Well UNIT LETTER <u>G</u> <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>1980</u> FEET FROM THE <u>East</u> LINE, SECTION <u>3</u> TOWNSHIP <u>24-S</u> RANGE <u>28-E</u> NMPM.	10. Field and Pool, or Wildcat <u>Malaga Atoka</u> (Gas)
15. Elevation (Show whether DF, RT, GR, etc.) 3041' KB	12. County Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Squeeze Atoka perms. 11,672-86'. Drill out & test to 4000#. Drill out 25' cmt cap & retrieve Baker RBP @ 11,800'. Run 2-3/8" & 2-7/8" tbg and On-Off tool to catch Baker Lok Set Pkr @ 12,282'. Pull plug in F Profile and swab Morrow perms. 12,424-12,901'. Return to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Raf H. Chapp TITLE Engineer - Agent DATE 7-23-85

Original Signed By
Les A. Clements

APPROVED BY Supervisor District II

CONDITIONS OF APPROVAL, IF ANY:

JUL 29 1985