P. TRIBUTION           T. FE           F. E	NEW MEXICO OIL CO	NSERVATION COMMISSION	Form C-103 Supersedes Old C-102 and C-103 Effective 1-j-65
U.S.G.S.			5a. Indicate Type ofase
			State Fee 2
OPERATOR	• .		5. State Oll & Gas Le ise No.
SUNDRY	NOTICES AND REPORTS C	N WELLS	<u> </u>
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT			- AHHHHHHH: HHH
OIL X GAS WELL		KECENTS	7. Unit Agreement Name
2. Name of Operator	OTHER-	750 4 4 1001	8. Form or Lease Name
HNG OIL COMPANY		DEC 1 1 1981	Kelly 5
Address of Operator		O. C. D.	9. Well No.
P. O. Box 2267, Midland,	Texas 79702	ARTESIA OFFICE	. 2
Location of Weil C 16	50 Wes		10. Field and Pool, or Wildcat
UNIT LETTER 16	FEET FROM THE	LINE AND PEET PR	Herradura Bend Delawar
North	5 23S	28E	
LINE, SECTION	TOWNSHIP	RANGE NMP	<i>**</i> Ω\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\
	15. Elevation (Show wheth	er DF, RT, GR, esc.)	12. County
	3023' Gr	·	Eddy
Check A	ppropriate Box To Indicate	Nature of Notice, Report or C	ther Data
NOTICE OF INT	FENTION TO:	SUBSEQUE	NT REPORT OF: 7/23/81
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	
TEMPORARILY ABANDON		COMMENCE DRILLING OPNS.	ALTERING CASING Plug and Abandonmilat
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB	FLUG AND ABANDONMENT
		· · · · · · · · · · · · · · · · · · ·	
		OTHER	
OTHER		OTHER	
7. Describe Proposed or Completed Oper	rations (Clearly state all pertinent d		
	rations (Clearly state all pertinent d		
7. Describe Proposed or Completed Oper			
7. Describe Proposed or Completed Oper work) SEE RULE 1703. 11/25/81 - Well P&A 6:00	p.m.	etails, and give pertinent dates, includin	ng estimated date of starting any prove
7. Describe Proposed or Completed Oper work; SEE RULE 1703. 11/25/81 - Well P&A 6:00	p.m.		ng estimated date of starting any propo
7. Describe Proposed or Completed Oper work) SEE RULE 1703. 11/25/81 - Well P&A 6:00 Set cement retainer at 24	p.m. 403' - squeezed Delawa	etails, and give pertinent dates, includin	ng estimated date of starting any probo w/50 sx. Class H cement.
7. Describe Proposed or Completed Oper work) SEE RULE 1103. 11/25/81 - Well P&A 6:00 Set cement retainer at 24 Perf. 4 shots from 548' rubber plug at 400'.	p.m. 403' - squeezed Delawa - 550'; pumped 60 sx C	letails, and give pertinent dates, includin re perfs (2465' - 2471') lass H 2% CaCl 3BPM at 25	ng estimated date of starting any proposition of starting any proposition of starting any proposition of start w/50 sx. Class H cement
7. Describe Proposed or Completed Oper work; SEE RULE 1703. 11/25/81 - Well P&A 6:00 Set cement retainer at 24 Perf. 4 shots from 548'	p.m. 403' - squeezed Delawa - 550'; pumped 60 sx C	letails, and give pertinent dates, includin re perfs (2465' - 2471') lass H 2% CaCl 3BPM at 25	ng estimated date of starting any proba w/50 sx. Class H cement.
7. Describe Proposed or Completed Oper work) SEE RULE 1703. 11/25/81 - Well P&A 6:00 Set cement retainer at 24 Perf. 4 shots from 548' rubber plug at 400'.	p.m. 403' - squeezed Delawa - 550'; pumped 60 sx C % CaCl at 90' to surfac	etails, and give pertinent dates, includin re perfs (2465' - 2471') lass H 2% CaCl 3BPM at 25 ce.	ng estimated date of starting any proposition of starting any proposition of starting any proposition of start w/50 sx. Class H cement
7. Describe Proposed or Completed Oper work) SEE RULE 1703. 11/25/81 - Well P&A 6:00 Set cement retainer at 24 Perf. 4 shots from 548' rubber plug at 400'. Spotted 15 sx. Class H 22 Welded on plate and dry-	p.m. 403' - squeezed Delawa - 550'; pumped 60 sx C % CaCl at 90' to surfac -hole marker; cut off a	etails, and give pertinent dates, includin re perfs (2465' - 2471') lass H 2% CaCl 3BPM at 25 ce.	ng estimated date of starting any proposition of starting any proposition of starting any proposition of start w/50 sx. Class H cement
7. Describe Proposed or Completed Oper work) SEE RULE 1103. 11/25/81 - Well P&A 6:00 Set cement retainer at 24 Perf. 4 shots from 548' rubber plug at 400'. Spotted 15 sx. Class H 25	p.m. 403' - squeezed Delawa - 550'; pumped 60 sx C % CaCl at 90' to surfac -hole marker; cut off a	etails, and give pertinent dates, includin re perfs (2465' - 2471') lass H 2% CaCl 3BPM at 25 ce.	ng estimated date of starting any proposition of starting any proposition of starting any proposition of start w/50 sx. Class H cement
7. Describe Proposed or Completed Oper work) SEE RULE 1703. 11/25/81 - Well P&A 6:00 Set cement retainer at 24 Perf. 4 shots from 548' rubber plug at 400'. Spotted 15 sx. Class H 22 Welded on plate and dry-	p.m. 403' - squeezed Delawa - 550'; pumped 60 sx C % CaCl at 90' to surfac -hole marker; cut off a	etails, and give pertinent dates, includin re perfs (2465' - 2471') lass H 2% CaCl 3BPM at 25 ce.	ng estimated date of starting any proposition of starting any proposition of starting any proposition of start w/50 sx. Class H cement
7. Describe Proposed or Completed Oper work) SEE RULE 1703. 11/25/81 - Well P&A 6:00 Set cement retainer at 2 Perf. 4 shots from 548' rubber plug at 400'. Spotted 15 sx. Class H 2 Welded on plate and dry-	p.m. 403' - squeezed Delawa - 550'; pumped 60 sx C % CaCl at 90' to surfac -hole marker; cut off a	etails, and give pertinent dates, includin re perfs (2465' - 2471') lass H 2% CaCl 3BPM at 25 ce.	ng estimated date of starting any proba w/50 sx. Class H cement.
7. Describe Proposed or Completed Oper work; SEE RULE 1703. 11/25/81 - Well P&A 6:00 Set cement retainer at 2 Perf. 4 shots from 548' rubber plug at 400'. Spotted 15 sx. Class H 2 Welded on plate and dry-	p.m. 403' - squeezed Delawa - 550'; pumped 60 sx C % CaCl at 90' to surfac -hole marker; cut off a	etails, and give pertinent dates, includin re perfs (2465' - 2471') lass H 2% CaCl 3BPM at 25 ce.	ng estimated date of starting any probo w/50 sx. Class H cement.
7. Describe Proposed or Completed Oper work; SEE RULE 1703. 11/25/81 - Well P&A 6:00 Set cement retainer at 2 Perf. 4 shots from 548' rubber plug at 400'. Spotted 15 sx. Class H 2 Welded on plate and dry-	p.m. 403' - squeezed Delawa - 550'; pumped 60 sx C % CaCl at 90' to surfac -hole marker; cut off a	etails, and give pertinent dates, includin re perfs (2465' - 2471') lass H 2% CaCl 3BPM at 25 ce.	ng estimated date of starting any probo w/50 sx. Class H cement.
7. Describe Proposed or Completed Oper work) SEE RULE 1703. 11/25/81 - Well P&A 6:00 Set cement retainer at 2 Perf. 4 shots from 548' rubber plug at 400'. Spotted 15 sx. Class H 2 Welded on plate and dry-	p.m. 403' - squeezed Delawa - 550'; pumped 60 sx C % CaCl at 90' to surfac -hole marker; cut off a	etails, and give pertinent dates, includin re perfs (2465' - 2471') lass H 2% CaCl 3BPM at 25 ce.	ng estimated date of starting any probo w/50 sx. Class H cement.
7. Describe Proposed or Completed Oper work) SEE RULE 1103. 11/25/81 - Well P&A 6:00 Set cement retainer at 24 Perf. 4 shots from 548' rubber plug at 400'. Spotted 15 sx. Class H 22 Welded on plate and dry- No casing was recovered and the statement of the stat	p.m. 403' - squeezed Delawa - 550'; pumped 60 sx C % CaCl at 90' to surfac -hole marker; cut off a from this well.	letails, and give pertinent dates, includin re perfs (2465' - 2471') lass H 2% CaCl 3BPM at 25 ce. anchors.	ng estimated date of starting any probo w/50 sx. Class H cement.
7. Describe Proposed or Completed Oper work; SEE RULE 1703. 11/25/81 - Well P&A 6:00 Set cement retainer at 2 Perf. 4 shots from 548' rubber plug at 400'. Spotted 15 sx. Class H 2 Welded on plate and dry-	p.m. 403' - squeezed Delawa - 550'; pumped 60 sx C % CaCl at 90' to surfac -hole marker; cut off a from this well.	letails, and give pertinent dates, includin re perfs (2465' - 2471') lass H 2% CaCl 3BPM at 25 ce. anchors.	ng estimated date of starting any probo w/50 sx. Class H cement.
7. Describe Proposed or Completed Oper work) SEE RULE 1103. 11/25/81 - Well P&A 6:00 Set cement retainer at 24 Perf. 4 shots from 548' rubber plug at 400'. Spotted 15 sx. Class H 22 Welded on plate and dry- No casing was recovered and the statement of the stat	p.m. 403' - squeezed Delawa - 550'; pumped 60 sx C % CaCl at 90' to surfac -hole marker; cut off a from this well.	Te perfs (2465' - 2471') lass H 2% CaCl 3BPM at 25 ce. anchors.	ng estimated date of starting any propo w/50 sx. Class H cement.
7. Describe Proposed or Completed Oper work) SEE RULE 1103. 11/25/81 - Well P&A 6:00 Set cement retainer at 24 Perf. 4 shots from 548' rubber plug at 400'. Spotted 15 sx. Class H 22 Welded on plate and dry- No casing was recovered and the statement of the stat	p.m. 403' - squeezed Delawa - 550'; pumped 60 sx C % CaCl at 90' to surfac -hole marker; cut off a from this well.	Te perfs (2465' - 2471') lass H 2% CaCl 3BPM at 25 ce. anchors.	ng estimated date of starting any probo W/50 sx. Class H cement. O psi; stop top
7. Describe Proposed or Completed Oper work) SEE RULE 1103. 11/25/81 - Well P&A 6:00 Set cement retainer at 24 Perf. 4 shots from 548' rubber plug at 400'. Spotted 15 sx. Class H 22 Welded on plate and dry- No casing was recovered and the statement of the stat	p.m. 403' - squeezed Delawa - 550'; pumped 60 sx C % CaCl at 90' to surfac -hole marker; cut off a from this well.	Te perfs (2465' - 2471') lass H 2% CaCl 3BPM at 25 ce. anchors.	ng estimated date of starting any proba w/50 sx. Class H cement. 0 psi; stop top