CHRONOLOGICAL HISTORY

AFE No. 96-W1930-06-M Plug and Abandon Oscar State No. 1 Owen Mesa Field Eddy County, New Mexico

Location: Elevation: Total Depth: Plug Back: Perforations:	1,980 Ft. FNL and 1,980 Ft. FEL of Section 36, T24S - R29E 3,102 Ft. (Ground) 3,123 Ft. (RKB) 14,396 Ft. 10,650 Ft. Cherry Canyon 5,402ft 5,482ft. (OA) Wolfcamp 11,645ft 11,819ft. (OA) Atoka 12,729ft 12,737ft. (OA)
--	--

- 8/14/96 MI and RU Smith Brothers Casing Pullers, Inc.
- 8/15/96 GIH with 228 joints of 2-3/8 inch workstring.
- 8/16/96 Mud up. Mix and pump 25 sacks Class "C" cement from 7,211ft.-7,082ft. and 50 sacks Class "C" cement from 5,375ft.-5,270 ft. POOH with tubing. ND casing and weld on pull nipple. Tag plug at 5,186 ft. SDFWE.
- 8/19/96 Cut 7-5/8 inch casing at 4,814ft. Work casing. LD 42 joints.
- 8/20/96 POOH and LD additional 60 joints 7-5/8 inch casing.
- 8/21/96 Finish LD casing. Final count 39 joints Buttress thread and 80 joints 8rd thread. Tally 4,845 ft. GIH with tubing to 4,897 ft. Mix mud and pump 50 sacks Class "C" cement. WOC. Tag plug at 4,760 ft. Pump 50 sacks Class "C" cement at 3,370 ft. POOH 50 joints. WOC. SDFN.
- 8/22/96 GIH with tubing. Tag TOC at 3,228 ft. LD tubing to 572 ft. Pump 50 sacks Class "C" cement. WOC. Tag plug at 448 ft. Pump 25 sacks Class "C" surface plug. Install dry hole marker. SDFN.
- 8/23/96 RD all equipment. Clean location. Move off at 2:00 PM CDT.
- 8/26/96 Cover pit and cellar areas. FINAL REPORT.