

7. Based on log evaluation, run 5-1/2" 17# N-80 FJ liner. Top of liner to be 300' inside 7-5/8" casing. Cmt w/ 325 sxs "H" with 5% KCL, 0.6% CFR-2, 0.3% Halad-22A and retarder. Displace cement with clean, fresh water treated with 2% KCL and non-emulsifying agent (2 gals NE per 1000 gals water).
8. Perforations, acid job, and additional stimulation to be determined after log evaluation.